

Category	Engine No.	Problem	Mileage
BRAKES & WHEELS	CH28304 TR7RV	rear wheel bearings failed	995
	XH02013 TRX75	speedo drive ring was backed out	1172
	PH00818 T150V	new tire--the tread was cracked	1700
	XH22485 T140V	bad front wheel bearings	2811
	BH25331 T140V	piston in master cylinder stuck	938
	AH23980 TR7RV	rear brakes squeal	652
	BH26024 T140V	brake shoe squeal	3207
	PH00518 T150V	rear wheel bearings bad	500
	NH18147 TR7RV	rear brake cam seized	4129
	AH23999 TR7RV	rear brake shoes making noise	682
	CH03513 T150V	rear wheel spokes broken	4133
	CH03513 T150V	bearing worn out	3819
	XH00428 T150V	rear wheel bearing seized	3320
	BH25457 T140V	right side bearing failed	3400
	CH03499 T150V	rear wheel bearings disintegrated	1370
	EH33515 T140V	rear brakes squeaking	867
	CH27127 T150	rear brake rod broke	4299
	NH17520 T140V	master cylinder cracked	2102
	DH31899 T140V	rear brakes don't hold	1226
	PH01487 TRX75	rear bearing failed	1052
	DH31663 T140V	bad rear wheel bearing - Jap type	1112
	AH23973 TR7RV	brake shoes on rear squeaked	1118
	CH29139 TR7RV	Loose rear wheel bearings	988
	CH27850 TR7RV	bad rear wheel bearings	2580
	DH31626 T140V	brake spring was broken in the drum	663
	AH23926 TR7RV	rear brake squeal	1720
	CH26969 T140V	rear wheel bearing failure	3509
	AH24030 TR7RV	brake squeal (rear)	4859
	DH32013 T140RV	bad rear wheel bearings	499
	BH25778 T140RV	wheel bearing seized	5006
	EH33055 T140V	rear brakes squeal	759
	DH31906 T140V	rear brake shoe had grease on them	1407
	CH27313 T140V	rear brakes squeal	1082
	CARBURETOR	NH00374 TRX75	connection tubes were cracked to carbs
EH32451 T140RV		carburetors poorly, mod. air cleaners	874
EH33521 T140V		carburetors poorly, mod. air cleaners	166
EH32702 T140V		carburetor bad distorted	736
XH22663 T140V		carb. poorly, modify air cleaners	1147
EH32902 T140V		change jetting on two carbs.	559
EH33549 T140V		carburetors poorly, clean carbs	538
CH29261 TR7RV		carb. poorly, clean carbs.	1993
EA32653 T140V		carb. rich	146
CH27351 T140V		carb. leaking gas at jet inspection cover	1266
DH31937 T140V		carb. poorly, reset floats	1310
AH24033 TR7RV		carb. poorly, mod. air cleaners	3732
JH15644 T100R		gas leaking from float bowls	883
XH22730 T140V		carbs leaking at float bowl	3930
NH18524 T100R		carb float was sticking	889
AH23582 T140V		carburation rich/replace with cleaner slides	2980
KH16460 T100R ✓		plugged idle jets	608
DH31705 T140V		bike not accelerating well-poor carburation	527
PH18901 T100R		carb rich/drop needles	202
CH29370 TR7RV		carburetion too weak	664
PH01443 TRX75		rubber manifolds of carburetors cracked	1749

Category	Engine No.	Problem	Mileage
CARBURETOR (con't)	CH29818 TR7RV	float bowl gasket leaking	1459
	XH22130 T140V	carb. leaking R/R float	200
	NH17185 T140V	carburetor leaking, R/R float	1166
	PH01210 TRX75	carb. slide sticking	440
	NH00714 TRX75	carburetors dirty	203
	CH26952 T140V	quits at 90 M.P.H. R/R with '72 cleaners	2150
	DH32279 T140V	bad carburetor	272
	NH00294 TRX75	carb. slides sticking	1888
	EH33128 T140V	'O' ring between carb. & manifold	987
	BH26260 T140RV	carburetor leaking, R/R float	434
	EH04546 T150V	carbs. leaking	109
	EH32655 T140V	float leaks	536
	DH31870 T140V	cut larger breather holes in aircleaners	518
	XH22539 T140V	carburetion rich	531
	AH23811 TR7RV	throttle sticks	2610
	CONTAMINATION	DH31740 T140V	no oil pressure - dirt in oil pump
DH30062 TR7RV		oil pump contaminated	472
PH19370 TR5T		oil pump contaminated	498
DH31899 T140V		swarf in pump	1126
EH32718 T140V		contamination--oil pump	500
CH27374 T140RV		swarfing oil pump	487
JH15997 T100R		contaminated oil pump	422
EH33052 T140V		contaminated oil pump	94
EH32558 T140V		contaminated oil system	100
GH34782 TR7RV		contamination in oil system	504
CH28491 TR7RV		contaminated oil pump	503
DH32093 T140V		contaminated oil pump	56
EH32558 T140V		contaminated oil system, R/R oil pump	10
XH02604 TRX75		contaminated engine, R/R crankshaft etc.	912
ELECTRICS	PH20566 TR5T	ignition switch defective	230
	CH03495 T150V	short in wiring harness	849
	PH19087 TR5T	speedometer bulb burnt out	1495
	JH33172 T140V	cells in battery are dead	1183
	EH33172 T140V	stop light bulb burnt out	1183
	AH23373 T140RV	improper trigger point for pressure switch	3214
	AH23373 T140RV	rear brake light switch broken	3214
	AH23373 T140RV	battery dead - sulfated	3214
	JH15923 T100R	battery does not stay charged	4242
	EH32940 T140V	battery sulfated	1278
	EH32792 T140V	brake light switch inoperative	1078
	EH32792 T140V	auto-advance sticking	1078
	DH31645 T140V	diode shorted	678
	DH04337 T150V	worn point blocks	1400
	NH17738 T140V	battery will not hold charge	1345
	AH23580 T140V	white & yellow wire broken in harness	3123
	BH25988 T140V	autoadvance broke	361
	DH31660 T140V	terminal zener diode came off	2600
	KH16760 TR5T	harness rubbed through at battery/caused short	1430
	AH23272 T140V	headlight bulb blown	4401
	AH23192 T140V	wire harness shorted	981
	CH03742 T150V	battery sulfated	3187
	CH03742 T150V	L/handlebar dip switch bad	3187
EA32653 T140V	headlight bulb blown	146	
CH27351 T140V	blown turn signal bulb	1266	

Category	Engine No.	Problem	Mileage
ELECTRICS (con't)	EH32925 T140V	battery defective	63
	CHO3688 T150V	headlight bulb blown	1130
	PH18803 T100R	kill button shorting out	894
	BH02070 T150V	ignition points closed up	1198
	EH32331 T140RV	bad battery	1409
	BH25746 T140V	battery sulfated	1900
	EH04466 T150V	tail light reflector broken	792
	EH04466 T150V	horn, no note	792
	DH30626 TR7RV	tail light, speedo, turn signal bulbs blown	818
	EH05148 T150V	point wire under gas tank not connected	10
	EH05148 T150V	flasher lamp unit housing stripped	10
	EH33072 T140V	wire broken off condenser	1650
	AH23769 TR7RV	blown head lamp bulb	3307
	EH33019 T140RV	terminal threads on battery stripped	0
	NH00248 TRX75	ignition switch not working	3014
	BH26228 T140V	major short in main harness	370
	EH32783 T140V	tail light bulb burnt out	440
	CH28605 TR7RV	vent tube came off battery	909
	CH28804 TR7RV	all bulbs blown- cause unknown	995
	EH33521 T140V	battery dead	169
	EH33521 T140V	diode short circuit	169
	NH17992 TR7RV	blown T.L. bulb	2860
	NH00248 TRX75	lead wire wore through under seat	3014
	EH32681 T140V	bulb burned out (directional)	36
	JH16276 T100R	R/R poor fuse assembly	628
	AH24069 TR7RV	short in tail light	1204
	AH24069 TR7RV	short in flasher lamp	1204
	JH15831 T100R	bad coil	1295
	JH15831 T100R	short in main harness	1295
	NH18483 T100R	wiring harness shorted	1602
	BH26318 T140V	ignition switch shorted out	2548
	DH31889 T140V	battery would only hold 9 volts	2100
	EH33549 T140V	blown headlight bulb	538
	DH03621 T150V	446 bulb blown	470
	KH16465 T100R	autoadvance sticking	1783
	PH18676 T100R	major short in main harness	180
	AH23209 T140RV	shorted out diode	2270
	DH32217 T140V	sulfated battery	0
	GH04783 T150V	battery defective	527
	CH27470 T140V	short in headlight	1118
	BH02285 T150V	short in wire harness under tank	520
	XH21405 TR7RV	short in wiring in headlite	1514
	CH26857 T140V	directional signal cracked	1525
	DH31569 T140V	bad diode	791
	EH32558 T140V	coil shorted	1050
	EH32563 T140V	R/handlebar switch contacts bad	643
	AH23231 T140RV	bulb burned out - 504	2015
	JH16277 T100R	sulphated battery	3780
	DH03659 T150V	sulphated battery	1425
	EH32902 T140V	brake switch cracked	559
	EH32558 T140V	cable harness oil soaked	10
	CH27809 TR7RV	faulty front brake switch	479
	NH18517 T100R	zener diode shorted	0

Category	Engine No.	Problem	Mileage
ELECTRICS(con't)	NH00194 TRX75	bad battery	1719
	XH00754 T150V	point striker blocks wearing down	2734
	AH24775 TR7RV	break in ground wire to tail lite	857
	CH28364 TR7RV	battery will not hold a charge	1025
	EH32803 T140V	stop light switch rear body broken	589
	EH32803 T140V	low beam out on headlamp	589
	EH32803 T140V	tail light bulb blown	589
	CH27089 T140RV	blown headlamp bulb	3365
	PH00978 TRX75	ground wire for cylinder broken	1282
	DH30637 TR7RV	battery won't hold charge	487
	AH23791 TR7RV	headlite bulb blew out	2516
	DH32223 T140V	defective battery	722
	AH24977 T140V	battery sulfated	2599
	AH24977 T140V	tail light reflector broken	2599
	DH30702 TR7RV	bad coil	906
	XH22366 T140V	open coil	1803
	CH28894 TR7RV	loose spark plug ends	1755
	CH27089 T140RV	blown tail lamp bulb	3365
	AH23831 TR7RV	bad diode	1117
	DH31870 T140V	H/L bulb burned out	518
	BH02088 T150V	tail light inoperative - repair broken wiring	1451
	NH17917 T140V	battery sulphated	2459
	AH25248 T140RV	H. L. bulb faulty	1134
	DH03963 T150V	horn fell apart	620
	CH33150 T140V	battery broke - acid damage	697
	XH22420 T140V	horn not working	2413
	DH32288 T140V	points closing up	283
	CH27402 T140V	open circuit in zener diode	2380
	AH24028 TR7RV	headlight shell clip had cut the light wires	2382
	NH18212 TR7RV	bad 54033667 switch	550
	AH23472 T140V	battery had a dead cell	800
	AH24349 TR7RV	oil pressure switch wouldn't work	3365
	BH25825 T140V	battery went bad	1392
	AH23960 TR7RV	battery sulfated	1503
	DH30637 TR7RV	horn won't beep	487
	DH04125 T150V	flasher inoperative	1486
	AH02158 T140V	battery will not hold charge	2695
	BH26020 T140V	faulty flasher	952
	DH30678 TR7RV	bad handlebar kill switch	861
	CH27192 T140V	battery charge defect	543
	BH26633 T140V	sulfated cells in battery	338
	AH25265 T140V	bad 34815 switch	1743
	CH28673 TR7RV	battery cells sulfated	1954
	NH17954 TR7RV	shorted out point to coil wire	1500
	DH20395 TR7RV	defective flasher unit	1050
	DH31663 T140V	flasher switch defective	1112
	AH24504 T140V	battery won't accept charge	883
	AH23050 T140V	battery dead cells	1397
	AH23383 T140V	parking, head lite, speedo bulbs blown	721
	XH21320 TR7RV	battery not taking full charge	1167
	XH21320 TR7RV	poor ground on zener diode	1167
	XH21320 TR7RV	brown lead connection in T/L improper	1167
	DH30315 TR7RV	battery would not hold charge	754

Category	Engine No.	Problem	Mileage
ELECTRICS	EH01262 T150V	battery won't hold charge	1675
	DH31977 T140V	broken wire in turn signal switch	6
	JH75873 T100R	turn signals inoperative, R/R switch	1397
	BH25381 T140V	battery sulfated	938
	CH03438 T150V	tail lights falling apart	998
	NH17441 T140V	headlite bulb burned out	3479
	XH00348 T150T	open circuit wiring harness	2171
	EH32783 T140V	dip beam on headlight burnt out	43
	XH21201 TR7RV	short tail light assembly	3201
	DH32179 T140V	bad turn signal switch	839
	AH25053 T140V	headlight low beam and speedo light out	602
	DH29951 TR7RV	head lamp bulb blown	720
	AH01815 T150V	tail light broken inside	1228
	DH30693 TR7RV	fuse holder wires burned	1338
	CH28600 TR7RV	repair burnt wire in head lamp	987
	PH01291 T150V	battery not charging	4015
	AH01238 T150V	short in wiring harness at headlight	1427
	CH28406 TR7RV	oil pressure switch shorted out	950
	AH24245 TR7RV	rectifier shorted	675
	DH30079 TR7RV	short in wire to horn switch	1428
	AH23556 T140V	brake switch defective	521
	KH16595 T100R	wire broken on rectifier	1410
	AH24737 TR7RV	headlight bulb burned out	1966
	BH25591 T140V	diode not grounded	1507
	BH02435 T150V	weld horn bracket on frame	2639
	XH00325 T150V	bad coil	1136
	AH23980 TR7RV	battery not hold charge	652
	AH01322 T150V	flasher defective	2656
	AH24046 TR7RV	dead cell in battery	462
	XH20752 TR5T	rear tail lamp no ground	2312
	EM32956 T140RV	flasher unit defective	741
	EH04897 T150V	bad battery	923
	AH24323 T140V	battery will not take charge	1035
	AH24520 T140V	lens cracked	316
	AH25165 T140V	battery sulfated	2341
	DH04124 T150V	pinched harness at fork stop	50
	DH03759 T150V	battery sulphated	430
	AH01663 T150V	battery would not hold charge	603
	AH23352 T140V	blown head lamp bulb	1888
	AH23352 T140V	blown 382 bulbs	1888
	EH05287 T150V	bad zener diode	375
	CH03503 T150V	horns vibrated and broke	950
	AH24893 TR7RV	battery case rubbed completely through	950
	CH01791 T150V	point blocks worn & broken	560
	DH31766 T140V	bad turn signal switch	1009
	AH23438 T140V	head light bulb burned out	4017
	AH23438 T140V	headlight bulb burned out	3255
	JH15924 T100R	wires were broken loose at tail lamp	3800
	JH15924 T100R	battery would not hold charge	3800
	AH24399 TR7RV	bad 34815 switch	1421
	AH24399 TR7RV	head lamp bulb blown	1421
	DH30092 TR7RV	battery will not hold charge	813
	AH23187 T140	defective battery	1466
	AH23187 T140	blown tail lamp bulb	1466

Category	Engine No.	Problem	Mileage
ELECTRICS (con't)	AH23187 T140	blown head lamp bulb	1466
	DH31601 T140V	battery case cracked	1362
	DH32556 TR7RV	blown head lamp bulb	1006
	NH18198 TR7RV	blown tail lamp bulb	2332
	NH18198 TR7RV	weak advance springs	2332
	CH29095 TR7RV	bad turn flasher bulbs	247
	CH29819 TR7RV	turn indicator fell off	86
	CH28617 TR7RV	battery wouldn't hold charge	1468
	CH26828 T140RV	RH turn signals not working--faulty switch	3670
	AH24676 TR7RV	horn wouldn't take current	651
	NH00961 TRX75	advance sticking	2191
	AH23413 T140V	battery sulfated	2140
	BH25869 T140RV	bad flasher	1609
	DH04249 T150V	horns not working	2276
	AH24171 T140V	bad battery	500
	DH32090 T140V	battery case cracked	1388
	DH32090 T140V	rear brake light switch broken	1388
	DH30281 TR7RV	defective battery	486
	CH27406 T140V	defective battery	1541
	BH02137 T150V	tail light out	2400
	CH29722 TR7RV	flasher open	8
	EH04546 T150V	short in wiring harness--rubbed against steering	109
	CH27340 T140V	zener diode bad	1444
	XH02050 TRX75	blown 966 bulb	610
	CH03353 T150V	wiring harness short at steering head	2285
	XH22730 T140V	flasher bulb burnt out	3930
	CH03509 T150V	sulfated battery	474
	EH33002 T140V	turn signal wire open in harness	1320
	XH00415 T155V	brake in harness at steering head	1043
	BH25470 T140RV	open 54033667 switch	1104
	CH28618 TR7RV	battery wouldn't hold charge	464
	DH30462 TR7RV	parking light bulb burnt out	969
	EH32718 T140V	battery charge defect	500
	NH17441 T140V	oil leak behind contact breaker assembly	3479
	DH29898 TR7RV	diode short circuit	500
	AH23438 T140V	headlight bulb blown	2707
	CH03507 T150V	condensers went bad fried points	1686
	DH30360 TR7RV	defective battery	237
	BH25400 T140V	defective battery	832
	EH23531 T140V	clutch dogs not operating properly	186
	EH32585 T140V	blown headlite bulb	557
	EH32585 T140V	tail light bulb out	557
	JH15992 T100R	coil shorted	2805
	AH24350 TR7RV	defective battery	599
	CH28911 TR7RV	defective battery	240
	CH28137 TR7RV	broken wire under gas tank	4243
	XH22809 T140V	bad battery	4552
	XH21509 TR7RV	bad battery	2287
	NH18536 T100R	short in electrical system R/R harness	571
	BH02380 T150V	condenser blade broken off--seized engine	2700
	PH04462 T150V	bad rectifier	906
	CH27877 TR7RV	defective battery	528
	AH23695 T140V	bad battery	544
	CH03566 T150V	wire in kill button was unsoldered	42

Category	Engine No.	Problem	Mileage
ELECTRICS (con't)	CH27310 T140RV	oil pressure switch inoperative	1227
	JH16124 T100R	hub of advancer assembly loose	4950
	AH24502 T140	advance unit froze	2229
	EH32710 T140V	defective battery	1011
	AH24037 TR7RV	horn wire shorting to head lamp	1435
	XH00338 T150V	open circuit in kill button	1235
	XH00338 T150V	flasher relay shorted	1235
	AH24826 TR7RV	short in harness	569
	XH22384 T140V	bad cells in battery	250
	AH23900 TR7RV	bracket on stop switch broken	760
	NH18098 TR7RV	diode short circuit	4347
	EH32890 T140V	tail lite nuts fell off	807
	AH23582 T140V	446 & 380 bulbs blown	2718
	DH32025 T140V	battery won't hold charge	506
	DH32025 T140V	replace flasher unit	506
	EH32741 T140V	contact breaker points burned	527
	PH19238 TR5T	broken wire to taillight	524
	KH16460 T100R	broken ground in taillight	608
	AH25285 T140V	dead battery cells	617
	CH03648 T150V	turn signal vibrated off	696
	AH25668 T140V	battery dedad - bad cell	4397
	CH26791 T140V	bad 31899 swtich	1104
	DH31779 T140V	stator burned out	1146
	CH03372 T150V	bad turn signal H/B switch	1232
	KH16595 T100R	stator not charging	1272
	DH32177 T140V	diode grounded	221
	CH27891 TR7RV	R/R pressure switch	619
	KH16955 TR5T	T/L does not work	2015
	BH02370 T150V	flasher body stripped	2203
	AH23519 T140V	open alternator	4095
	BH02253 T150V	battery charge defect	317
	DH30046 TR7RV	horn no note - R/R horn	837
	DH03937 T150V	battery sulfated	1113
	DH30098 TR7RV	bad headlight switch	239
	PH19097 TR5T	open wire in taillight	3691
	JH15732 T100R	headlight bulb blown	569
	XH20854 TR5T	tail light quit working - broken wire	783
	XH21136 TR7RV	short in zener diode	1867
	XH21160 TR7RV	not charging - broken wire	2140
	NH17257 T140V	battery bad	1408
	AH02473 T150V	bad coil	3165
	AH25090 T140V	baffles loose & rattling in mufflers	1129
	EH33170 T140V	contact breaker points burned	364
	XH21432 TR7RV	flashing indicator switch inoperative	3665
	AH23475 T140V	battery had a sealing defect	1146
	AH23475 T140V	T/L bulb blown	1146
	CH27489 T140V	found broken wires in dimmer switch	2178
	PH01303 T150V	battery sulfated	2360
	PH01303 T150V	brake switch broken	2360
	DH30389 TR7RV	brake switch broken	1701
	DH30389 TR7RV	flasher quit working	1701
	XH22384 T140V	battery cracked - extensive acid damage	200
	JH15847 T100R	rectifier was defective	3360
	EH32877 T140RV	tail light bulb blown	272

Category	Engine No.	Problem	Mileage
ELECTRICS(con't)	NH17587 T140V	battery would not hold charge	550
	XH00411 T150V	ignition switch open	500
	NH00935 TRX75	internal ground in coil	2887
	PH00975 TRX75	bad diode	632
	DH30533 TR7RV	battery has two dead cells	1742
	NH17340 T140V	504 bulb blown	1519
	NH17340 T140V	bulb blown - tail lamp	1519
	NH17340 T140V	blown headlamp bulb	1519
	AH23578 T140V	brake switch shorted out	925
	CH03158 T150V	flasher quit working	1380
	DH32167 T140V	blown head lamp bulb	1288
	CH27747 TR7RV	turn signal bulbs blown	585
	CH27747 TR7RV	head lamp bulb blown	585
	CH29718 TR7RV	H/L bulb blown	886
	BH25428 T140V	H/L bulb blown	1121
	BH25703 T140V	low beam out	850
	PH01487 TRX75	bulbs blown--speedo, tach, H/L	1052
	DH31559 T140RV	auto-advance unit sticking	6918
	XH20951 TR5T	ground wires broke off inside headlight	2027
	DH31899 T140V	battery sulfated	1226
	PH18714 T100R	short in white wire inside headlight	1976
	NH18135 TR7RV	battery sulfated	3384
	NH18135 TR7RV	wire harness burned completely	3384
	CH03623 T150V	R/R broken condenser	8
	EH33492 T140V	T/L bulb burnt out	565
	EH33492 T140V	H/L bulb burnt out	565
	EH33492 T140V	T/S bulbs burnt out	565
	AH24672 TR7RV	battery will not hold charge	2064
	NH17449 T140V	points burnt very rapidly	3138
	CH29278 TR7RV	battery would not hold a charge	610
	BH25448 T140RV	battery sulfated	1952
	AH23621 T140V	faulty flasher unit	1980
	NH17595 T140RV	bad diode	2763
	PH18908 T100R	headlamp bulb burnt out	5215
	PH18908 T100R	ignition coil leaking fluid	5215
	EH32633 T140V	plastic fuse holder broken	17
	DH04215 T150V	condenser male connector broken off	10
	PH05079 T150V	condenser male connector broken off	130
	JH15788 T100R	L.H handle switch came apart	1451
	DH04328 T150V	short in alternator wire	1433
	DH04050 T150V	wiring harness shorts	422
	XH22421 T140V	auto advance unit sticks	3291
	DH04049 T150V	short in handlebar switch	0
	CH28863 TR7RV	no vent hole in battery	2100
	AH01546 T100V	battery sulfated	8
	DH03994 T150V	weak A/A springs	536
	DH03994 T150V	headlight bulb burnt out	536
	BH35698 TR7RV	blown instrument lites	1305
	DH04113 T150V	flasher quit working	701
	PH18908 T100R	tachometer bulb blown	3902
	AH24502 T140V	zener diode defective	2801
	KH00170 TRX75	coil shorted internally	2614
	CH29158 TR7RV	battery wouldn't hold charge	177

Category	Engine No.	Problem	Mileage
ELECTRICS (con't)	AH23628 T140V	harness shorting out	1872
	AH23628 T140V	R/handlebar switch inoperative	1872
	XH22663 T140V	auto advance sticking	1022
	PH00950 TRX75	rectifier grounded	2850
	BH26262 T140V	short in wiring	670
	DH29961 TR7RV	battery was sulfated	562
	DH29961 TR7RV	bad flasher	562
	EH32858 T140V	blown H/L bulb	912
	BH25855 T140V	bad H/L switch	2864
	CH05493 T150V	flasher doesn't work	902
	AH24504 T140RV	battery would not hold charge	361
	CH03536 T150V	turn signals not working--shorted out	1320
	PH19682 TR5T	capacitor shorted out	11
	GH05257 T150V	headlight wiggles--clips installed wrong	11
	GH05257 T150V	kill switch not working - broken wire	11
	GH34739 TR7RV	headlight switch on handlebar not working	10
	GH05096 T150V	bad flasher	436
	BH25853 T140V	taillight & directional bulbs blown	1117
	XH21706 TR7RV	open ignition switch	479
	XH21161 TR7RV	bad cell in battery	2019
	EH04970 T150V	battery broken	0
	GH34540 TR7RV	wire unsoldered in L/Handerbar switch	1
	BH02266 T150V	wire behind tail light bulb came undone	1375
	XH00606 T150V	oil press light comes on	3211
	EH33397 T140V	battery bad	1871
	CH03566 T150V	diode wire rubbed into on front part of frame	580
	BH25749 T140V	stop light switch defective	1134
	EH56435 TR7RV	headlight bulb burned out	2134
	EH56435 TR7RV	tail light bulb burned out	2134
	DH30318 TR7RV	tail light bulb burned out	1853
	AH23105 T140V	battery would not hold charge	1067
	NH17519 T140V	bad flasher	1375
	NH17519 T140V	side panel had cut wire	1375
	JH16287 T100R	open in main harness	1928
	CH29434 TR7RV	battery cracked	510
	CH27515 T140V	battery won't hold charge	689
	XH21530 TR7RV	horn did not work	322
	DH03560 T150V	oil pressure switch bad	470
	AH23272 T140V	flasher case cracked	4401
	AH23438 T140V	speedo & tail light bulbs blown	4544
	JH15654 T100R	bad rectifier	2473
	CH03536 T150V	turn signals not working--shorted out	1320
	EH29051 TR7RV	battery won't charge	1886
	EH33096 T140V	replace stop light bulb	300
	CH27313 T140V	harness shorting out	1082
	CH27825 TR7RV	auto-advance sticking	932
	ENGINE	AH24777 TR7RV	oil consumption, R/R rings
PH00510 TRX75		oil consumption & piston noise	499
AH02119 T150V		broke two push rods	913
CH03189 T150V		restriction in oil feed line	858
JH16267 T100R		rocker box has not been drilled for oil passage	1179
EH04916 T150V		rocker adjuster broken	500
DH30641 TR7RV		rocker adjuster hole stripped	639
EH33363 T140V		defective rocker ball on rocker arm	656

Category	Engine No.	Problem	Mileage
ENGINE	AH24825 T140V	oil consumption, R/R rings	1125
	JH15873 T100R	bent push rod	1397
	XH21653 TR7RV	engine out of time	4054
	CH03356 T150V	#2 cylinder burned oil-replace guides, rings	2348
	CH29784 TR7RV	head gasket cracked - leaking	2269
	NH18369 T100R	unable to keep R.H. inlet valve adjusted	852
	XH21521 TR7RV	bad pistons rings	769
	JH16185 T100R	push rod & rocker arm broken	1104
	CH29791 TR7RV	excessive oil consumption	1658
	CH26992 T140V	excessive smoking R/R rings	1241
	BH25657 T140V	oil pump seized	200
	AH24871 TR7RV	intake guides went bad	409
	XH21657 TR7RV	cylinder head leaks	2132
	JH15973 T100R	defective push rod	1257
	AH24825 T140V	high oil consumption R/R rings	950
	BH25730 T140V	piston rings would not seal	1162
	XH00348 T150T	threads stripped out of rocker box	2171
	PH18830 T100R	head gasket blown	1501
	BH26019 T140RV	head gasket blown	2851
	XH21196 TR7RV	right exhaust push rod broken	2042
	JH15997 T100R	bent push rod	422
	PH18914 T100R	push rod has shortened approx. $\frac{1}{8}$ "	1356
	JH15719 T100R	top of the tappet broke off	326
	JH15753 T100R	push rod ends worn at letter	2168
	JH15804 T100R	locating pin for A/A sheared	2783
	JH15788 T100R	bent push rods & broken tappets	515
	AH25150 T140V	bad oil pump	48
	JH16136 T100R	push rods length short	1581
	BH02138 T150V	cyl. stud & head bolt were stripped	1821
	CH03164 T150V	rocker box heli-coil improperly installed	765
	PH19248 TR5T	push rod collapsed	566
	DH30216 TR7RV	blown head gasket	4028
	AH23571 T140V	blown head gasket	4630
	XH21144 TR7RV	mainbearing lefthand seized	65
	DH03804 T150V	engine noisy - R/R cam intermediate gear	12
	DH04097 T150V	bolt broken in rocker box	1225
	KH16503 T100R	push rod too short from factory	1464
	PH20119 TR5T	mainshaft nut primary side came loose	1200
	KH16895 TR5T	excessive oil consumption	1561
	EH33558 T140V	oil pump not working	11
	XH22366 T140V	R/R rings	1504
	JH16220 T100R	short push rods	2021
	KH16742 TR5T	head gasket leaked	2076
	EH33211 T140V	oil pump bad	12
	NH17681 T140V	conn. rod cap loose	2010
	JH15670 T100R	bad push rods	1504
	JH15648 T100R	intake tappets both broken	1529
	KH16591 T100R	hole in piston	1017
	NH17210 T140V	smokes -- rings not sealed	1963
	BH25367 T140V	oil consumption -- barrel scored	1459
	NH18079 TR7RV	cylinder head gasket leak	5725
	PH00978 TRX75	valves leaking also push rod bent	1282

Category	Engine No.	Problem	Mileage	
ENGINE(con't)	JH15667 T100R	head gasket leak	1106	
	KH17005 TR5T	chain tensioner adjuster missing	563	
	JH16338 T100R	short push rods	861	
	BH25668 T140V	engine noisy bad main bearing	3180	
	BH25474 T140V	R/R crankcase, cam bushes misaligned	942	
	AH22280 T140V	blown head gasket	4250	
	AH23791 TR7RV	timing off - retarded	2516	
	DH29827 TR7RV	resurface head-warped very badly	3968	
	NH17992 TR7RV	oil consumption, .080" ring gap	2860	
	AH23710 T140V	bad engine vibration--balanced crank	2176	
	EH33363 T140V	defective rocker ball on rocker arm	656	
	KH17089 TR5T	both intake pushrods collapsed	1682	
	EH33290 T140V	push rod came apart rocker cracked	1321	
	EH33385 T140RV	no oil pressure, bad ball seats	500	
	JH15750 T100R	push rod end worn	1791	
	EH32356 T140V	valve dropped, keeper was missing	271	
	CH29261 TR7RV	oil consumption, R/R rings & reseal valves	1993	
	EXHAUST	CH29187 TR7RV	muffler mount broke	251
		CH29285 TR7RV	exhaust clip cracked	518
		CH27747 TR7RV	small hole in pipe where welded together	585
AH23263 T140V		E12465--finned clip breakage	741	
BH26024 T140V		ext. pipe stay broken	3783	
CH03566 T150V		tail pipe had a crack at weld	42	
XH20894 TR5T		right hand exhaust pipe cracked	839	
NH17754 T140V		exhaust pipes cracked at front motor mounts	1299	
PH18908 T100R		exhaust headed pipes won't stay in head	3902	
JH15614 T100R		leak in right ext. pipe	1628	
NH18098 TR7RV		silencer baffles loose	4347	
DH31660 T140V		left silencer cracked at mount	2120	
XH21642 TR7RV		right exhaust pipe has holes in welds	611	
CH28974 TR7RV		left exh. pipe cracked	1468	
AH25207 T140V		exhaust bracket broken	2460	
NH17296 T140RV		R/H exh. pipe crack at bend by crossover	726	
NH17296 T140RV		R/H ex. pipe cooler ring broken	726	
DH29827 TR7RV		finned ex. pipe fitting split	3968	
CH29447 TR7RV		exh. leak in weld of right pipe	1107	
NH18079 TR7RV		exh. pipe fin clips had metal flaws	5725	
CH29698 TR7RV		weld at head pipe cracked	1030	
EH04972 T150V		exh. pipe cracked at weld	500	
AH23272 T140V		exh. pipe cracked at head	4401	
XH21175 TR7RV		L/H exh. pipe weld leaking	757	
CH29248 TR7RV		left exh. pipe broke	1436	
XH00985 T150V		muffler bracket broken	2250	
BH25853 T140V		bad weld at R/H exhaust pipe	1117	
BH25554 T140V		poor welds on R/ H exh. pipe	614	
CH29051 TR7RV		exhaust pipe broken	1886	
BH25537 T140V		right exhaust pipe bad weld	650	
FINISH	CH03507 T150V	chrome peeling on exhaust pipes	474	
	CH03356 T150V	red faded on gas tank	2348	
	GH34676 TR7RV	exhaust pipe had peeling chrome	0	
	BH02125 T150V	chrome peeling from ex. pipe	912	
	CH27011 T140V	paint coming off gas tank	1610	
	CH27011 T140V	fender brace chrome coming off	1610	
AH23406 T140V	D4148 decal came off	771		

Category	Engine No.	Problem	Mileage	
FINISH(con't)	CH27882 TR7RV	front fender chrome blemished	1416	
	GH34870 TR7RV	gas tank paint blistered	6	
	AH24508 T140V	seat trim strip cracked	2124	
	KH26672 T140V	chrome peeling off front rim	3471	
	DH03839 T150V	chrome had on front fender	8	
	AH23520 T140V	chrome peeling off tach bracket	315	
	BH25913 T140V	chrome peeled off	1465	
	BH25878 T140V	defective chrome on clutch lever	926	
	DH31851 T140V	chrome came off rear fender	575	
	EH32507 T140V	chrome peeling off muffler	0	
	DH04302 T150V	paint faded	0	
	CH27809 TR7RV	chrome peeling off flasher	479	
	DH32026 T140V	both fuel taps leaking	351	
	GH24918 TR7RV	fuel tank paint faded	3	
	EH05028 T150V	chrome lifted on front fender	516	
	CH29051 TR7RV	chrome came off rear rim	1886	
	EH32449 T140V	chrome peeled off the front fender	2100	
	CH03660 T150V	mudguard front chrome lifted	500	
	AH01542 T150V	very poor paint on gas tank	0	
	EH32464 T140V	chrome peeling off front fender	1130	
	FORKS & SHOCKS	EH32787 T140V	oil leak front forks	1428
		BH02376 T150V	fork seals leak	2080
		BH25797 T140V	fork leaks	2773
		XH22369 T140V	fork seal leaking	2255
		CH28894 TR7RV	bad fork seals	1755
AH24504 T140V		fork seals leaking	883	
BH26697 T140V		fork seals leak	796	
EH32747 T140V		fork seals leak	1157	
DH31880 T140V		forks leaking	2123	
DH03848 T150V		forks leaking oil	1143	
DH32223 T140V		fork seals leaking	722	
XH00773 T150V		fork leaks	3206	
CH29276 TR7RV		fork seals leaking	687	
AH24092 TR7RV		fork seal leaks	876	
AH23945 TR7RV		fork seal leaking	1830	
AH25248 T140RV		fork seal leaking	1134	
CH03442 T150V		front forks leaking	1033	
NH18211 TR7RV		front fork caps leaking oil	1403	
BH02116 T150V		fork seal leaking	1165	
AH23926 TR7RV		forks leaking	1720	
DH31471 T140V		fork seals leaking	1000	
NH00248 TRX75		fork leaks	3014	
DH30637 TR7RV		fork seals leaking oil	487	
AH23679 T140V		leaky front forks	2481	
BH25365 T140V		fork seals leak	308	
CH27471 T140RV		leaking fork seals	572	
CH28931 TR7RV		forks leaking	774	
CH30634 TR7RV		forks leak	605	
EH32902 T140V		forks leak oil	559	
DH31906 T140V		fork seal leaking	1407	
EH04916 T150V		fork leaking	500	
CH27875 TR7RV		fork seals leaking	932	
CH03563 T150V		fork seal leaks	520	
DH03560 T150V	fork seals leaking	559		

Category	Engine No.	Problem	Mileage
FORKS & SHOCKS (con't)	AH24175 T140V	fork seals leaking	226
	EH01262 T150V	fork seals leaking	1675
	CH27930 TR7RV	fork leaking	991
	AH24858 TR7RV	right fork seal leak	1500
	CH28789 TR7RV	right fork leak	1750
	DH31559 T140RV	forks leaking oil	6947
	XH02618 TRX75	fork leaking oil	1208
	XH00325 T150V	leaking fork seals	1136
	CH03438 T150V	leaking fork seal	998
	DH30027 TR7RV	fork seals leaking	829
	DH30027 TR7RV	oil pressure switch leaking.	829
	CH29171 TR7RV	fork seals leaking	2772
	NH00193 TRX75	forks leaking	871
	BH26024 T140V	forks leak	3783
	CH29784 TR7RV	fork seals leaking	2269
	DH30443 TR7RV	fork seal leaking oil	1357
	DH30493 TR7RV	forks leaking at seals	989
	AH24507 T140V	fork leaks	1693
	CH27118 T140V	fork leaks	327
	DH24144 T150V	fork seal leak	696
	CH29580 TR7RV	fork seal leakage	916
	BH25636 T140V	fork seals leaking	1560
	BH26003 T140RV	fork seals leaking	1691
	CH27706 TR7RV	fork leaking	2788
	CH29516 TR7RV	fork leaking oil	1415
	AH24226 TR7RV	fork seals leaking	1739
	CH29661 TR7RV	repair oil leak at top of forks	836
	AH23592 T140RV	forks leak	1702
	AH24251 T140V	forks leaking oil	1246
	AH24757 T140V	forks leaking	2436
	CH28850 TR7RV	fork seals leaking	421
	DH30563 TR7RV	fork seals leaking	224
	PH19169 TR5T	fork seals leak	518
	BH25566 T140V	fork seals leaking	1356
	CH29379 TR7RV	forks leaking oil	664
	CH27054 T140V	fork seal leaking	2397
	JH15997 T100R	fork leaks oil	422
	AH25143 T140V	fork seal leaks	150
	EH32601 T140V	fork seals leaking	858
	CH30499 TR7RV	front fork leakage	872
	KH16987 TR5T	forks leaking	1015
	BH02353 T150V	shock leaked	450
	DH30216 TR7RV	fork seals leaked	4028
	CH03648 T150V	fork seals leak	696
	EH32296 T140V	fork seal leaking	998
	EX21496 TR7RV	leaking forks	1207
	AH24436 T140V	fork seals leaking	1410
	BH25446 T140V	forks leaking	2357
	EH32864 T140V	fork seals leaking	497
	BH25509 T140V	fork seals leaking	1165
DH31654 T140V	fork seals leaking	762	
AH23994 TR7RV	fork seals leak	1050	
CH27885 TR7RV	fork oil seal leaking	118	

Category	Engine No.	Problem	Mileage
FORKS & SHOCKS (con't)	DH03560 T150V	fork seals leaking	559
	JH15985 T100R	fork seals leaking	3077
	CH28867 TR7RV	fork leaks	1778
	DH30167 TR7RV	both forks leaking	1513
	CH29566 TR7RV	fork seals leaking	2006
	EH04972 T150V	fork seals leaking	500
	BH25554 T140V	forks leak	614
	AH23272 T140V	fork seals leaking	4401
	DH31725 T140V	forks leak	1935
	DH29939 TR7RV	fork leaks	1954
	EH32618 T140V	fork seal leaking	1072
	AH23112 T140V	fork leaks	0
	NH17847 T140V	front fork leaking	954
BROKEN F/FENDERS & BRACKET	BH25497 T140V	fender stay cracked	2844
	CH29171 TR7RV	center stay broke	2772
	XH20782 TR5T	fender mount cracked	2312
	CH28690 TR7RV	front fender bracket broken	4207
	CH28409 TR7RV	fender bracket broke	2021
	CH26731 T140V	mud guard front stay cracked	1184
	AH24672 TR7RV	fender braces broken	2064
	DH30443 TR7RV	front stay broke	1357
	CH29344 TR7RV	fender brace broken	977
	CH29845 TR7RV	fender brace broke	1353
	NH17317 T140V	fender stays broken at welds	5452
	AH24757 T140V	three stays on front fender broken	2436
	AH24502 T140V	broken fender braces	2801
	CH29022 TR7RV	lower fender brace cracked & broken	1802
	NH17735 T140V	fender braces broke	5200
	AH25068 T140V	front fender bracket broke	4397
	AH23623 T140V	cracked mud guard stay	4500
	DH30216 TR7RV	cracked mud guard stays	4028
	EH32956 T140RV	weld broke on bottom stay	741
	NH17977 TR7RV	fender stay broken	4842
	BH25381 T140V	rear fender brace broke	938
	AH23245 T140V	center fender stay cracked	1633
	CH29698 TR7RV	center mount on front fender cracked	1030
	AH23710 T140V	fender bracket broken	2176
	CH28414 TR7RV	broken front fender brackets	1808
	EH32558 T140V	fender brace broke at weld	1050
	AH21548 TR7RV	front fender stays broke	3137
NH17296 T140RV	fender brace broken	726	
KH17045 TR5T	front fender split	1006	
BH26427 T140V	both fender braces broke	1866	
FRAME & COMPONENTS	XH02592 TRX75	horn broke off	1429
	AH23710 T140V	lifting handle broken	2176
	DH04277 T150V	fork lock not working	634
	BH25497 T140V	chainguard cracked	2844
	CH03744 T150V	R/box allens leak	135
	CH03353 T150V	horn fell off	2285
	AH01322 T150V	horn bracket broken	2656
	XH01637 T150V	horn bracket broken	5944
	JH15879 T100R	steering head lock defective	605
	EH04897 T150V	reflector mounting plate vibrated loose	923
CH03335 T150V	brackets broken on two horns	2373	

Category	Engine No.	Problem	Mileage	
FRAME & COMPONENTS (con't)	CH03442 T150V	hooters fell off	1033	
	XH00754 T150V	frame horn bracket broke	2734	
	DH04199 T150V	fork lock was defective	1008	
	DH04137 T150V	license plate brackets vibrated off	620	
	CH26794 T140V	rear frame fracture	2503	
	DH31870 T140V	fork lock inoperative	8	
	BH25682 T140V	defective steering head lock	317	
	PH18908 T100R	dipstick broken off	3902	
	DH04061 T150V	horn bracket broke	2352	
	CH29608 T140V	frame leaking oil at weld	0	
	CH03389 T150V	reflector lost from oil cooler	547	
	CH29549 T140V	frame leaking oil at weld	0	
	AH01720 T150V	side cover cracked	1300	
	DH32179 T140V	treads bad at oil fill	837	
	NH00266 TRX75	reflector fell off	2022	
	BH25629 T140RV	fork lock inoperative	3872	
	CH29732 TR7RV	air filter cover cracked	3199	
	AH24681 TR7RV	steering lock did not align with hole	783	
	XH01088 T150V	frame horn brackets broke	3142	
	BH25421 T140V	side cover cracked	550	
	EH04466 T150V	reflector fell off oil cooler	792	
	PH18686 T100R	fork lock not working	499	
	AH02434 T150V	fork lock not working	588	
	DH30199 TR7RV	leaking oil at frame steering head, R/R frame	240	
	CH05493 T150V	sidestand spring broke	902	
	GEARBOX & CLUTCH	CH28609 TR7RV	clutch rod worn	1348
		DH03915 T150V	clutch rod broke, bearing seized	1512
		DH31563 T140V	clutch push rod worn	1012
		CH28654 TR7RV	mainshaft key sheared	641
		DH31569 T140V	clutch slippage	791
CH03742 T150V		clutch pull rod broken & bearing seized	3187	
CH29261 TR7RV		clutch slippage	1993	
DH32093 T140V		broken first gear	56	
AH24362 TR7RV		nut on mainshaft came loose	1650	
KH16760 TR5T		camplate index plunger stuck in case	1430	
EH33464 T140RV		high gear oil seal leak	10	
BH25629 T140V		master link broke	120	
CH29470 TR7RV		high gear oil seal leak	165	
EH32618 T140V		clutch pushrod worn	1092	
AH23534 T140V		mainshaft key sheared	3426	
JH15900 T100R		primary adj. rod stripped	453	
NH17210 T140V		gearbox locked up	1963	
NH17885 T140V		broken tooth on layshaft	1024	
EH33392 T140V		clutch push rod worn	506	
CH28974 TR7RV		transmission won't shift	1468	
NH17481 T140V		layshaft failed	1321	
PH01364 T150V		clutch would drag	968	
DH30224 TR7RV		camplate bad in 2nd gear	1773	
CH27046 T140V		tooth broken off mainshaft	2677	
NH17909 T140V		key sheared on mainshaft	947	
XH00429 T150V		transmission needle bearings bad	2915	
DH04010 T150V		clutch bearing seized	1444	
EH32862 T140V		clutch push rod worn	106	

Category	Engine No.	Problem	Mileage
GEARBOX & CLUTCH (con't)	NH00263 T150V	jumping out of third	1014
	AH23900 TR7RV	broken teeth on gearbox gears	760
	DH32025 T140V	gearbox selection difficult into neutral	506
	DH20615 TR5T	locked in gear	1401
	NH17735 T140V	layshaft gear broke	5200
	NH17929 TR7RV	broken L/S & M/S highgear	1080
	NH17278 T140V	thrust washer on layshaft slipped off pin	510
	CH29771 TR7RV	clutch key sheared	748
	AH24157 T140V	broken tooth on layshaft	777
	PH19625 TR5T	clutch slip due to weak springs	1202
	CH26785 T140V	broken gears in transmission	509
	AH24328 TR7RV	M/S second broke	2300
	KH00155 TRX75	gearbox shift poor - R/R outside cover	586
	NH17289 T140V	mainshaft key sheared	1060
	AH24877 TR7RV	hard to shift	1058
	AH01575 T150V	bearing seized breaking clutch rod	307
	NH18191 TR7RV	clutch hub key was sheared	1275
	PH00994 T150V	clutch slipping	1618
	BH25727 T140V	gearbox teeth broken	1169
	NH17969 TR7RV	sheared clutch key	1126
	NH18211 TR7RV	layshaft gear tooth broken	1403
	XH00574 T150V	thrust bearing frozen	3045
	CH27850 TR7RV	tooth broken off layshaft	1740
	BH25509 T140V	broken layshaft	1607
	AH24447 T140V	nut came off mainshaft on T/S	1400
	JH16036 T100R	clutch friction material coming off	218
	NH17827 T140V	shifts hard or not at all into 5th gear	2576
	KH16475 T100R	high gear bush lock up on main shaft	1801
	AH23684 T140V	clutch cable broke	5081
	EH32932 T140V	threads in clutch pressure plate stripped	543
	BH02255 T150V	seized clutch bearing, broken pull rod	2057
	BH25291 T140V	clutch adjuster cross threaded	923
	BH02287 T150V	transmission tries to lock up	2474
	EH33473 T140V	clutch key sheared	413
	NH17179 T140V	broken tooth on L/S	2189
	AH24694 TR7RV	worn clutch push rod	1221
	CH29775 TR7RV	clutch key sheared	351
	DH03963 T150V	bad clutch chatter	620
	CH27071 T140V	teeth broken on layshaft	1823
	BH25993 T140V	gearbox selection difficult	1242
	AH22280 T140V	broken teeth layshaft	4250
	JH16076 T100R	seized camplate	590
	DH03659 T150V	clutch pull rod broken	1425
	BH26616 T140V	broken teeth high gear M/S	1236
	AH24286 TR7RV	sheared clutch key	572
	AH23214 T140RV	sheared clutch key	1602
	CH27116 T140V	clutch rod worn	1538
	JH15985 T100R	teeth broken off transmission gears	3077
	CH33174 T140V	14-0403 clutch not missing during assembly	198
	AH24504 T140RV	gear selector plunger was stuck	361
	DH03587 T150V	broken pull rod	1476
	PH01477 TRX75	slipping clutch, R/R oil seal & clutch	1800
NH00479 TRX75	oil on clutch from defective seal	1852	

Category	Engine No.	Problem	Mileage
GEARBOX & CLUTCH	AH24825 T140V	clutch drag	1125
	CH03231 T150V	clutch pull rod broken	2970
	KH16987 TR5T	chain adj. plate broke	1015
	CH28690 TR7RV	clutch rod worn	4207
	XH27216 TR7RV	shifts poorly - stiff	3248
	DH30493 TR7RV	clutch key sheared	989
	XH01503 TRX75	primary chain broke	495
	CH27035 T140V	clutch noise - chattering	2300
	BH25974 T140RV	broken L/S	603
	GH34682 TR7RV	clutch rod worn	1148
	CH27520 T140V	tooth broken off 1st gear on mainshaft	1012
	BH26043 T140V	broken layshaft	680
	EH33148 T140V	clutch key sheared	621
	PH10180 T150V	tore teeth off layshaft	1938
	XH00433 T150V	broken L/S gear	3989
	EH33301 T140V	noise in gearbox	538
	BH25624 T140V	clutch not disengaging	1648
	DH30443 TR7RV	clutch slips badly	1357
	DH30544 TR7RV	gears worn	306
	PH04355 T150V	bearing in center of clutch seized	1370
	DH31940 T140V	soft clutch rod	946
	CH27071 T140V	drive chain broken	1444
	DH30479 TR7RV	clutch key sheared	158
	EH32433 T140V	teeth broken in trans	573
	DH31520 T140V	mainshaft nut worked loose	839
	DH31520 T140V	clutch push rod worn	839
	DH03862 T150V	nut came loose on clutch pull rod	600
	BH02251 T150V	noisy primary drive	500
	CH27091 T140V	clutch push rod defective	541
	EH32775 T140V	clutch lever not crimped properly	1462
	KH17154 T140V	gearbox locked up	1709
	DH32067 T140RV	poor gear selection	1709
	CH51199 T140V	clutch key sheared	620
	GH34684 TR7RV	key broken on mainshaft	08
	CH27870 TR7RV	gear on layshaft seized	501
	BH25430 T140V	layshaft gear breakage	1162
	CH38789 TR7RV	vibration R/R clutch hub	1750
	CH26951 T140V	end burned off clutch	1731
	CH29549 TR7RV	clutch rod worn	980
	NH17233 T140V	trans locked up	259
HANDLEBAR/CONTROLS	AH24549 T140V	clutch cable broken	5275
	DH03773 T150V	clutch cable broken	556
	BH02137 T150V	clutch cable broken	3002
	CH28966 TR7RV	throttle cable outer casing binding	106
	CH27116 T140V	clutch cable broken	1538
	AH24868 TR7RV	clutch cable broke	2700
	EH32858 T140V	broken clutch cable	912
	PH00510 TRX75	throttle cable bad	499
	DH31569 T140V	broken clutch cable	791
	CH29555 TR7RV	clutch cable broken	1344

Page 18

Category	Engine No.	Problem	Mileage
Handlebar/Controls (con't)	AH24493 T140V	clutch cable broken	1921
	NH00961 TRX75	broken clutch cable	2287
	AH24012 TR7RV	throttle cable snapped	3069
	XH21171 TR7RV	clutch cable broken	2777
	BH02255 T150V	clutch cable broken	2020
	EH32126 T140V	clutch cable broken	1730
	EH32545 T140V	broken clutch cable	1573
	CH03629 T150V	clutch cable broken	1223
	BH25291 T140V	handlebar mount rubbers worn out	923
	CH29008 TR7RV	clutch cable broken	3400
	PH00994 T150V	clutch cable wire broken	1618
	AH24092 TR7RV	broken clutch cable	876
	DH31692 T140V	r/r twin throttle cables broken	1604
	AH25265 T140V	broken clutch cable	1743
	AH24658 TR7RV	broken clutch cable	1623
	AH24111 TR7RV	broken clutch cable	2178
	CH29718 TR7RV	tach cable broken	886
	DH30493 TR7RV	clutch cable wire broken	989
	AH01815 T150V	clutch cable defective	1228
	BH26682 T140V	clutch cable broken	1534
	BH25357 T140V	clutch cable broken	2140
	BH25946 T140V	clutch cable broken	89
	AH23438 T140V	clutch cable broken	3995
	XH21610 TR7RV	broken clutch cable	3775
	PH18934 T100R	broken throttle cable	2125
	AH23023 T140V	clutch cable broken	1525
	DH03912 T150V	broken clutch cable	1200
	AH24506 T140V	throttle cable broken	902
	PH18796 T100R	choke cable broken	178
	DH30479 TR7RV	broken clutch cable	383
	EH32499 T140V	broken clutch cable	1600
	PH01138 TRX75	clutch cable frayed	738
	JH15879 T100R	brken wire in clutch cable	605
	BH25698 T140V	brken clutch cable	1305
	CH03158 T150V	clutch cable broke	1380
	DH29936 TR7RV	clutch cable broken	1370
	XH02688 TRX75	clutch cable broken	885
	XH21585 TR7RV	clutch cable frayed	3017
	BH25446 T140V	clutch cable broken	2298
	BH25918 T140V	r/r clutch cable	1640
	CH29564 TR7RV	clutch cable broken	2100
	XH22108 T140V	clutch cable broken	1300
	XH99767 T140V	clutch cable broken	1248
	NH00953 TRX75	clutch cable broken	2840
	AH25098 T140V	choke cable broken	2932
	DH25734 T140V	clutch cable broken	1907
	AH25168 T140V	throttle cable broken	4397
	CH29123 TR7RV	clutch cable broken	3100
	DH04199 T150V	clutch cable broken	1910
	CH27542 T140V	clutch cable broken	1445
CH27450 T140V	clutch cable broken	1750	

Category	Engine No.	Problem	Mileage
HANDLING PROBLEMS	AH23192 T140V	wobbler, R/R rear tire	981
	DH30693 TR7RV	front wheel out-of-balance	1925
	CH28963 TR7RV	wobbler, R/R rear tire	817
	PH00252 TRX75	front wheel out-of-balance	640
	EH04972 T150V	both wheels out of balance	500
	AH24550 T140V	wobbler, R/R rear tire	684
	XH02618 TRX75	wobbler, R/R front tire	1893
	EH32507 T140V	wobbler, R/R rear tire	615
	AH23231 T140RV	front wheel out of balance	2015
	EH32451 T140\$V	wobbler, R/R rear springs	874
	XH22667 T140V	wobbler, changed fork oil	698
	CH29059 TR7RV	wobbler, R/R rear tire	510
	XH27476 TR7RV	wobbler, R/R rear tire	3600
	XH22663 T140V	wobbler, R/R rear tire & balanced it	1144
	AH24032 TR7RV	wobbler, replaced rear springs	3532
	AH24032 TR7RV	rear wheel out-of-balance	3532
	XH22663 T140RV	wobbler, R/R rear springs & tighten rear spokes	1125
	XH22342 T140V	wobbler, R/R rear tire	718
	AH25270 T140RV	wobbler, R/R rear tire	684
	BH26225 T140RV	wobbler, R/R front tire	4020
	NH00714 TRX75	wobbler, R/R rear tire	204
	CH29732 TR7RV	wobbler bad rear bearings, R/R rear tire	3199
	BH25365 T140V	wobbler, R/R rear tire	305
	AH23831 TR7RV	wobbler, R/R front tire	1117
	DH31626 T140V	wobbler R/R rear tire	663
	AH23081 T140V	wobbler, R/R rear tire	1209
	DH30468 TR7RV	wobbler, R/R rear tire	553
	BH25968 T140V	wobbler, R/R rear tire	562
	CH03387 T150V	both tires out of balance	3128
	XH01088 T150V	wobbler, R/R front tire	3142
	BH26027 T140V	wobbler, R/R rear tire	580
	CH29813 TR7RV	wobbler, R/R rear tire	1277
	CH29171 TR7RV	wobbler, R/R rear tire	2772
	AH23980 TR7RV	wobbler, R/R front & rear tires	652
	EH33128 T140V	wobbler, R/R rear tire	987
	AH23438 T140V	wobbler, R/R rear tire	2707
	PH01210 TRX75	wobbler, R/R rear tire	440
	CH29597 TR7RV	wobbler, R/R rear tire	413
	AH23601 T140V	wobbler, R/R rear tire & swinging arm	1085
	CH26952 T140V	wobbler, R/R rear tire	2150
	DH31626 T140V	wobbler, R/R front & rear tires	1484
	CH21820 T140RV	wobbler, R/R rear tire	1526
	DH31958 T140V	wobbler @ 60 M.P.H., R/R rear tire	2115
	CH29769 TR7RV	wobbler, R/R rear tire	1247
	GH35222 TR7RV	wobbler, R/R rear tire	147
	AH23192 T140V	wobbler, R/R rear tire	1742
	DH30033 TR7RV	wobbler, R/R rear tire	207
	AH24327 TR7RV	wobbler @ 70 M.P.H., R/R rear tire	2784
	DH32280 T140V	rear wheel out of alignment	675
	XH02034 TRX75	wobbler, R/R rear tire	597
	DH31649 T140V	wobbler, R/R rear tire	1241
	AH25196 T140V	wobbler, R/R rear tire	589

Category	Engine No.	Problem	Mileage
HANDLING PROBLEMS (con't)	NH01222 TRX75	wobbler R/R rear tire	2836
	CH27882 TR7RV	front wheel out of balance	1416
	DH30443 TR7RV	wobbler, repositioned fork stanchions	1357
	DH31699 T140V	wobbler, tightened steering head bearings	496
	XH27216 TR7RV	wobbler, R/R rear tire	3248
	BH26019 T140RV	wobbler, R/R rear tire	2851
	BH25925 T140RV	wobbler, R/R rear tire	1700
	XH21193 TR7RV	wobbler, R/R rear tire	4422
KICKSTART	PH04103 T150V	broken K/S spring	4638
	CH29504 TR7RV	K/S gear broken	500
	JH15985 T100R	kickstarter ratchet broken	3077
	GH05389 T150V	K/S return spring came off peg	132
	CH27346 T140RV	K/S gear broken	2519
	DH04137 T150V	kick start spring broken	1213
	PH19556 TR5T	K/S pawl broken	320
	DH31870 T140V	kickstarter pedal loose	518
	JH16101 T100R	K/S ratchet failed	2046
	AH23527 T140RV	broken kick spring	2792
	EH04874 T150V	K/S spring broken	196
	EH04874 T150V	K/S spring retaining peg too short	0
	DH04299 T150V	kick starter spring slips off	80
	BH25606 T140RV	kickstart ratchet teeth broken	1300
	DH31972 T140V	K/S spring broken	254
	XH22384 T140V	replace K/S spring	250
	CH29231 TR7RV	kick start gear broken	682
	PH01443 TRX75	kickstart gear tooth broken	1749
	PH19084 TR5T	pin bent not allowing pawl to work properly	1015
	CH28918 TR7RV	K/S ratchet gear broken	794
DH03893 T150V	K/S spring kept slipping off pin	30	
KH16532 T100R	kickstarter pawl worn out	1859	
XH00421 T150V	K/S spring broken	483	
AH23080 T140RV	K/S spring broken	1027	
CH28974 TR7RV	K/S not working	1468	
DH31839 T140V	K/S spring pin loosened	615	
XH21496 TR7RV	kickstart spring broken	1023	
EH55470 T120V	K/S broke	2000	
PH01135 TRX75	K/S nut loose	736	
XH21522 TR7RV	kickstart pinion gear teeth broken	1721	
MISSING/TRANSIT DAMAGE	DH31660 T140V	headlight & tail light were cracked at setup	2600
	GH05150 T150V	missing gear shift lever	0
	XH01066 T150V	scratched front fender	1
	EH04917 T150V	flashers damaged	0
	CH03225 T150V	gas tank, front brake hose damaged	0
	EH32681 T140V	battery broken in transit	0
	PH19080 TR5T	stop-tail lamp cracked	3
	EH33007 T120V	headlamp, front tire & flasher damaged	0
	GH34427 TR7RV	seat torn	0
	DH03743 T150V	tank dented in transit	0
	GH35349 TR7RV	received without tools or riders inst.	0
	GH35349 TR7RV	received without tools or riders inst.	0
	GH34878 TR7RV	gas tank, headlight, tail light damaged	0
CH29167 TR7RV	tach face broken	0	

Category	Engine No.	Problem	Mileage
MISSING/TRANSIT	DH30354 TR7RV	ruptured brake line	0
DAMAGE (con't)	EH34084 TR7RV	front brake hose & L/S ex. pipe damaged	0
	GH35181 TR7RV	gas tank & headlight lens damaged	0
	AH23578 T140V	tach & cable damaged	10
	EH32915 T140V	lead on switch assy. rubbed through	0
	CH27858 TR7RV	brake hose & switch lead damaged	0
	AH24566 T140V	hole in tank	0
	CH34789 TR7RV	headlight rim damaged	0
	GH05065 T150V	crate damage seat cover	0
	EH04883 T150V	damage to gas tank, mufflers, brake line	9
	EH04883 T150V	damage to seat cover & turn signals	9
	EH05176 T150V	damage to gas tank & one turn signal broken	8
	CH27593 TR7RV	headlite unit cracked & side cover damaged	0
	EH32305 T140V	tail lamps & turn flashers damaged	8
	DH31862 T140V	tail lamp damaged	9
	EH32890 T140V	tail lamp lens broken in shipment	5
	CH27174 T140V	clutch cable tail lamp lens missing	0
	EH34139 TR7RV	headlight lens cracked & turn signals damaged	5
	GH34808 TR7RV	damage to front fender & tail lamp	6
	GH35300 TR7RV	tank was damaged	0
	GH35124 TR7RV	tank damaged in crate	0
	DH30443 TR7RV	gas tank damaged & tail light broken	1357
	GH05533 T150V	missing tool kit	0
	GH34572 TR7RV	gas tank damaged	0
	EH05087 T150V	tail lamp damaged	0
	EH05087 T150V	gas tank & tail light damaged	0
	EH05087 T150V	gas tank & D/S panel damaged	0
	GH34720 TR7RV	seat was ripped at the seam & H/L shell broken	7
	DH04021 T150V	improper L/S exhaust system	0
	DH31699 T140V	gas tank damaged	496
	DH32070 T140V	paint on fuel tank scratched	0
	GH34427 TR7RV	tank, front brake hose & battery damaged	0
	XH21144 TR7RV	seat damaged in transit	65
	XH21528 TR7RV	dented & cracked primary case	0
	PH18830 T100R	oil tank damaged from shipping	1501
	CH03509 T150V	tool kit & manual missing	474
	DH30547 TR7RV	seat cover has hole	1250
	DH03804 T150V	flasher lamp wires broken	12
OIL LEAKS	EH33055 T140V	oil leak tappet block 'O' rings	759
	DH30172 TR7RV	oil leak at primary gasket	524
	CH27515 T140V	pressure switch leak	689
	AH24777 TR7RV	tappet guide block leaks	2200
	EH33521 T140V	replaced rocker gaskets	166
	XH22667 T140V	r/r primary gasket	698
	CH28931 TR7RV	primary leaking	774
	CH27470 T140V	rocker box oil leak	1118
	JH16076 T100R	oil leak at rocker box	590
	BH02285 T150V	oil leak at ex rocker cover	520
	XH21405 TR7RV	oil leak in primary cover	1514
	CH26857 T140V	oil leak at oil pressure switch	1525
	AH23456 T140V	r/r primary gasket	1650
	BH25748 T140V	tappet block 'O' ring bad	738

Category	Engine No.	Problem	Mileage
Oil Leaks (con't)	CH27340 T140V	oil leak under primary	1444
	XH02050 TRX75	oil leak - rocker box	610
	EH33392 T140V	base gasket leaking at cylinder joint	507
	DH04277 T150V	oil cooler leaking	634
	BH25913 T140V	tappet guide block oil leaks	1465
	XH21529 TR7RV	oil leak primary joing	517
	AH24175 T140V	tappet blocks leaking	2264
	AH23578 T140V	oil leaking rocker gaskets	9250
	CH27284 T140V	oil pressure switch leaks at term. end	680
	AH24857 TR7RV	oil leak - rocker box	1500
	DH30533 TR7RV	T/E oil leaks	1742
	XH02618 TRX75	rocker box leaking	1208
	XH00325 T150V	oil leak front rocker box	1136
	XH22730 T140V	rocker box to head joint leaking	3930
	BH25381 T140V	base gasket leaking	938
	XH00415 T150V	oil leak clutch housing	1043
	AH24046 TR7RV	oil leak primary cover	462
	EH53052 T140V	oil pressure switch leaks	94
	DH31699 T140V	primary case leak oil	496
	EH32956 T140V	oil sending unit leaking oil	741
	CH26952 T140V	point seal leaking	2150
	EH32718 T140V	oil pressure valve leaking	500
	JH15997 T100R	cracked primary case	422
	CH28581 TR7RV	oil leaking from k/s	1743
	CH29549 TR7RV	leaking oil from drive sprocket	980
	EH33002 T140V	oil leaking from push rod tubes	1320
	BH02137 T150V	valve cover gasket leak	2400
	DH30443 TR7RV	push rod cover seal leaks oil	1357
	AH25188 T140V	rockerbox gaskets leaking.	2020
	XH21657 TR7RV	oil leaks from push rod cover tubes	2132
	CH27928 TR7RV	leaking oil sending unit	842
	BH25544 T140V	base gasket leaking	2560
	BH25544 T140V	push rod tubes leaking	2560
	CH29466 TR7RV	leak at high gear	2954
	AH23849 TR7RV	rocker inspection cover gasket replaced	525
	CH03526 T150V	clutch rod seal leaking	959
	CH03526 T150V	rocker box gasket leaking	959
	CH03526 T150V	tach gear box leaking	959
	CH28675 TR7RV	oil pressure switch leaking	1092
	DH31594 T140V	oil leak primary cover gasket	189
	AH23980 TR7RV	cyl. base leaking oil	652
	AH23980 TR7RV	timing cover leaking oil	652
	DH29898 TR7RV	oil leak kickstart shaft	500
	DH29898 TR7RV	oil pressure valve leaking	500
	EH32783 T140V	tappet guide block leaking oil	43
	EH04950 T150V	tap end oil leaks	426
	XH00598 T150V	oil leak cover - rocker	50
	EH52678 T140V	pressure switch leaking	503
	AH24634 TR7RV	oil leak - ex. tappet guide	1553
	CH29610 TR7RV	prim. gasket leaking	1233
	EH33480 T140V	leaking oil through counter shaft sprk't	496

Category	Engine No.	Problem	Mileage
Oil Leaks (cont'd)	DH90489 TR5T	rocker box gasket leaking	874
	CH03438 T150V	t/e oil leaks	998
	CH03438 T150V	primary gasket leaks	998
	XH00348 T150V	oil leak - rocker box to head joint	2171
	DH30462 TR7RV	pressure switch leaking oil	969
	CH03231 T150V	oil leak at cyl. base	2970
	CH03744 T150V	r/box allens leak-	135
	CH03768 T150V	leaking oil-contact breaker seal	1088
	CH29344 TR7RV	oil leak - pressure switch	977
	NH00193 TRX75	rocker boxes leaking	871
	XH21196 TR7RV	transmission main shaft leak	2042
	JH15644 T100R	rockerboxes leaking	883
	XH21653 TR7RV	oil leak between r/box and cyl. head	4054
	XH20951 TR5T	tach. drive leaking	2037
	AH23406 T140V	pressure switch leaking	771
	AH24787 TR7RV	primary gasket replaced	1966
	XH00985 T150V	hole in crankcases	2250
	CH26858 T140V	trans. oil leak around c/shaft area	1339
	CH03413 T150V	oil leak at push rod tubes	1760
	BH02075 T150V	oil leak at push rod cover tubes	950
	XH22688 TRX75	inspection cover gasket leaking	1142
	DH30021 TR7RV	oil leak at tappet guide block	543
	DH30021 TR7RV	high gear oil leak	543
	CH28795 TR7RV	oil leak from vent tube under gas tank	623
	CH28654 TR7RV	oil leak from contact breaker seal	550
	CH28654 TR7RV	oil leak from c/shaft sprocket	550
	EH33272 T140V	oil leak from base gasket	513
	EH04846 T150V	oil leak at cyl. base gasket	980
	CH03150 T150V	oil leak from base gasket	1249
	BH01559 T150V	top end leaking	2620
	KH16649 TR5T	pressure switch leaking	241
	NH17989 TR7RV	petcock wore through oil line	752
	BH01640 T150V	point seal leak	1090
	NH17992 TR7RV	leaking point advancer seal	3009
	BH26600 T140V	pressure switch leak	723
	DH03746 T150V	oil leak at head gasket	621
	CH29457 TR7RV	point seal leak	803
	CH29068 TR7RV	pressure switch leak	1200
	NH18427 T100R	oil leak rocker boxjoint to cyl. head	1550
	CH27252 T140V	pressure switch leak	2864
	BH25470 T140V	Switch 54033667 open	1104
	BH02438 T150V	counter shaft seal leak	2639
	XH20782 TR5T	oil leak rocker box to head	2312
	CH27217 T140V	base gasket oil leak	2744
	PH01207 TRX75	rocker box leak	597
	PH04314 T150V	rocker box leak	573
	BH26662 T140V	point cam oil seal leak	840
	XH02013 TRX75	many top end oil leaks	1149
	DH30479 TR7RV	base gasket oil leak	272
	EH32368 T140V	push rod leaks	504
	EH32368 T140V	base gasket leaks	504
	JH15825 T100R	head gasket leak	1186

Problem	Engine No.	Problem	Mileage
Oil Leaks (cont'd)	CH26824 T140V	cylinder base gasket leak	5470
	CH26824 T140V	primary cover leak	5470
	CH26728 T140V	rocker box oil leak	747
	DH31899 T140V	sump leak	889
	DH31899 T140V	primary oil leak-gasket replaced	889
	CH29069 TR7RV	oil leak from mainshaft	1655
	AH23264 T140V	rocker box gasket leak	1852
	XH02594 TRX75	push rod tubes leaking	421
	CH26811 T140V	base gasket leak	1650
	DH31744 T140V	replaced rocker gaskets	546
	JH18960 T100R	push rod seals leaking	663
	BH30499 TR7RV	base gasket leaking	872
	JH15916 T100R	top end oil leaks	108
	DH30371 TR7RV	oil sending unit leaking	1060
	DH30371 TR7RV	replaced base gasket	1060
	CH26829 T140V	oil pressure switch leaking	866
	CH02958 T150V	oil leak timing cover	1136
	DH03855 T150V	oil pressure switch leaking	1216
	BH02178 T150V	rocker box leaking - Allen screws	2036
	NH18035 TR7RV	re-seal rocker box gaskets	1121
	XH00559 T150V	rocker box leaks	3191
	CH28871 TR7RV	leak at rocker boxes	1355
	CH28871 TR7RV	leak from primary case	1355
	CH28871 TR7RV	leak from timing cover	1355
	CH28871 TR7RV	leak at outer gearbox gasket	1355
	DH31497 T140V	cyl. base gasket leaking oil	1002
	DH31511 T140V	oil pressure switch leaking	352
	PH20024 TR5T	top end oil leak	2178
	PH20024 TR5T	oil leak on rocker box spindle	2178
	CH27084 T140V	pressure switch leaking	1321
	CH26991 T140V	top end oil leaks	1503
	PH30247 TR7RV	leakage at rear push rod 'O' ring	634
	CH27072 T140V	primary chain case gasket leak	632
	CH27072 T140V	leak rotor cover gasket	632
	NH17827 T140V	contact breaker oil seal leak	2522
	CH03744 T150V	top end oil leak	634
	CH03744 T150V	hole in oil line	634
	EH33056 T140V	primary cover oil leak - gasket	74
	KH16567 T100R	cracked rocker oil fee line	751
	DH32128 T140V	gearbox seal leaking	1080
	DH31605 T140V	oil pressure switch bad	1582
	CH26769 T140V	oil leak in primary cover	2727
	XH21656 TR7RV	clutch key sheared	2200
	NH17486 T140V	rocker box gaskets leak	2281
	DH04113 T150V	rocker boxes leaking	701
	CH03513 T150V	primary gasket leaks	4133
	JH16136 T100R	oil leaks - replaced top end gaskets	1581
	XH22136 T140V	push rod oil seals leaking	2280
	NH17275 T140V	output shaft seal leaking	3200
	AH25175 T140V	trans. oil leak from output shaft area	2911
	EH32866 T140V	oil seal behind points leaking	621
	NH17331 T140V	oil pressure switch leaking	3420

Category	Engine No.	Problem	Mileage
Oil Leaks (cont'd)	EH33122 T140V	leak at exhaust tappet guide	158
	DH29829 TR7RV	pressure switch leak	85
	DH29936 TR7RV	highgear oil seal leak	1370
	EH32890 T140V	r/b inspection gasket leak	807
	CH03164 T150V	oil tank cap leaking	765
	CH03164 T150V	oil leak r/b cover gasket	765
	AH23582 T140V	oil leaks base and head	2718
	AH25040 T140V	oil leak around tach drive unit	1827
	AH25040 T140V	oil leak around base gasket	1827
	PH19238 TR5T	oil leak around base gasket	524
	NH17929 TR7RV	oil leak at tappet guide block	1080
	DH31740 T140V	pressure switch leak	835
	AH24508 T140V	oil leak around seal in highgear	2124
	AH24508 T140V	pressure switch leak	2124
	KH16460 T100R	oil leak in pushrod tube	608
	BH25703 T140V	primary gasket leak	850
	PH19248 TR5T	pressure switch leak	566
	BH02353 T150V	r/b oil leak	450
	DH31660 T140V	pressure switch leak	2120
	AH25205 T140V	pressure switch leak	617
	XH02688 TRX75	r/b oil leak	885
	AH23571 T140V	porous crankcase	4629
	DH04097 T150V	rocker spindle 'O' rings leaking	1225
	DH04097 T150V	rocker box gaskets leaking oil	1225
	KH16503 T100R	feeler cap/tappet inspect. tap 'O'	1464
	KH16503 T100R	contact breaker oil seal leak	1464
	CH03372 T150V	rocker box gaskets leaking	1232
	CH03372 T150V	rocker spindle 'o' rings leak	1232
	CH26791 T140V	leaking pressure switch	1104
	PH01443 TRX75	rocker spindle 'O' ring leaking	1749
	PH01443 TRX75	rocker box gaskets leaking	1749
	CH29818 TR7RV	sump plate gasket leaking	1459
	CH27932 TR7RV	oil leak primary gasket	460
	CH03386 T150V	rocker box gasket leaking	1049
	CH27757 TR7RV	tappet guide block 'O' rings leak	1004
	CH29074 TR7RV	oil pressure switch leak	456
	DH18879 T100R	contact breaker seal leaking	1700
	DH30521 TR7RV	gasket primary side leak	558
	NH00272 TRX75	rocker box gaskets leaking	751
	AH00833 T150V	oil leaking into points cover	791
	CH28682 TR7RV	timing cover cracked near oil s'dr	433
	CH28682 TR7RV	oil sender switch leak	433
	CH29042 TR7RV	oil leak at tappet guide block	2918
	KH16541 T100R	oil leak contact breaker seal	482
	JH16063 T100R	rocker box leaking oil	1521
	DH31994 T140V	pressure switch leaking	680
	DH31994 T140V	crack in timing cover	680
	DH32280 T140V	c. b. seal bad	354
	DH30554 TR7RV	pressure switch leaking	500
	DH32200 T140V	oil pipe and union leak	701
	CH03453 T150V	oil leak rocker covers	2315
	CH03308 T150V	r/b oil leaks	283

Category	Engine No.	Problem	Mileage
Oil Leaks, (cont'd)	AH01714 T150V	primary cover gasket pinched	3315
	AH24338 TR7RV	oil leak-push rod tubes	1027
	CH28909 TR7RV	plug under main sprocket	1020
	KH16541 T100R	R & R auto adv. oil seal	482
	AH23997 TR7RV	push rod tube leak	1730
	AH23322 T140V	high gear oil seal leak	1071
	DH09125 T150V	warped r/b surfaces	1486
	AH23151 T140V	oil leak-push rod tubes	762
	CH28798 TR7RV	oil leaks out of base gasket	2998
	CH28570 TR7RV	crack in primary case	604
	BH02376 T150V	top end oil leaks	2412
	DH30599 TR7RV	oil pressure switch leaking	1167
	GH34712 TR7RV	rocker box oil leak	29
	DH03790 T150V	rocker box leak	756
	DH30004 TR7RV	oil leak primary case joint	696
	KH16527 T100R	push rod tubes leaking	197
	CH03574 T150V	oil pressure switch leaking	544
	XH00870 T150V	oil leak from pushrod tubes	1367
	CH27038 T140V	oil pressure switch leaking	1683
	JH15617 T100R	leak at rocker box	507
	GH05120 T150V	oil leak at push rod tubes	485
	CH29274 TR7RV	oil leak primary gasket	1406
	DH04256 T150V	oil leak at head gasket	3749
	NH18154 TR7RV	tappet guide block 'O' ring leaks	2666
	AH61639 T150V	oil leak head gasket	2785
	EH04741 T150V	oil cooler leak	598
	NH17296 T140V	point seal leak	726
	AH01799 T150V	rocker spindle 'O' rings leak	1372
	AH01799 T150V	rocker box gaskets leak	1372
	CH27371 T140V	primary cover gasket leak	796
	CH27371 T140V	rocker box gaskets leak	796
	CH27371 T140V	oil pressure sending switch leak	796
	EH33198 T140V	oil leak c/s sprocket	585
	EH32409 T140V	point seal leak	738
	KH17138 T140V	many top end oil leaks	1775
	KH17138 T140V	pressure switch oil leak	1775
	XH21678 TR7RV	rocker box oil leaks	231
	EH32429 T140V	cyl. base gasket oil leak	890
	EH32429 T140V	point cam oil seal leak	890
	AH24977 T140V	high gear oil seal leak	2599
	XH00773 T150V	oil leak in point area	3206
	AH23791 TR7RV	front p/r tube, head gasket leak	2516
	NH17954 TR7RV	timing cover oil seal faulty	1500
	BH25447 T140V	oil sender unit leaks	1489
	CH03491 T150V	rocker box gaskets leaking oil	508
	CH03491 T150V	rocker spindle 'O' rings leaking	508
	DH00978 TRX75	rocker spindle 'O' rings leaking	282
	NH18211 TR7RV	rocker box gaskets leaking	1403
	BH26606 T140V	oil leak rocker box	2263
	BH26606 T140V	primary gasket leak	2263
	CH27089 T140V	oil leak - oil pressure switch	3365

Category	Engine No.	Problem	Mileage
Oil Leaks (cont'd)	DN03848 T150V	oil leak rocker box joint	1143
	BH25623 T140V	oil pressure switch leak	3872
	EH32655 T140V	oil leak at base nuts	536
	BH25727 T140V	oil leak at base gasket	1169
	CH29008 TR7RV	tappet guide block leak	3400
	PH00994 T150V	oil leak at push rod tubes	1618
	CH27192 T140V	cyl. base leak	543
	XH22264 T140V	rocker gasket cover leak	527
	DH29836 TR7RV	oil leak from push rod tube	2680
	AH23994 TR7RV	oil leak at base gasket	1050
	NH17917 T140V	push rod seal leak	2459'
	CH29782 TR7RV	tappet guide block oil leak	4145
	DH31692 T140V	oil leak at base	1604
	BH02116 T150V	exhaust rocker box gaskets leaking	1165
	BH02088 T150V	top end oil leaks	1451
	DH31870 T140V	oil leak at alt. wire-thru c/s	518
	XH22539 T140V	r/r primary gasket	531
	CH29447 TR7RV	oil leak - tappet block	1107
	DH20395 TR7RV	rocker box cover leak	1050
	BH26308 T140V	oil leak rocker box to head	521
	DH31757 T140V	oil leak at tappet guides	888
	JH15878 T100R	oil sending switch leaking	682
	DH31979 T140V	many top end oil leaks	537
	CH29644 TR7RV	r/r primary gasket leak	0
	EH04820 T150V	rocker box gasket leak	764
	CH29164 TR7RV	oil pressure switch leak	1774
	BH02273 T150V	oil leak tappet guide block	1562
	GH04835 T150V	oil leak push rod tube	673
	AH24422 T140V	cyl base gasket leak	530
	AH24422 T140V	head gasket leak	530
	AH24422 T140V	rocker box gaskets leak	530
	CH27849 TR7RV	oil leak at tach. drive	500
	CH29200 TR7RV	alternator grommet leaking	3802
	DH04185 T150V	oil leak rocker spindle oil seal	1337
	XH00826 T150V	oil leak - top end	340
	EH04829 T140V	rocker gasket leak	521
	AH23811 TR7RV	rocker box gasket leak	2610
	CH29276 TR7RV	pressure switch leak	687
	CH29219 TR7RV	high gear oil seal leak	1455
	DH31795 T140V	base gasket leak	520
	EH04466 T150V	r/r base gasket	792
	AH23926 TR7RV	rocker box to head joint leak	1720
	AH24504 T140V	valve covers leaking	883
	CH26991 T140V	oil leak at seal-c/s sprocket	1657
	NH00248 TRX75	bad leak in cyl. base	3014
	DH32025 T140V	oil leak timing cover joint	506
	DH32025 T140V	base gasket oil leak	506
	KH16451 T100R	E7576 oil line leaking	1661
	AH01648 T150V	oil leak in rocker cover joint	1541

Category	Engine No.	Problem	Mileage
Oil Leaks (cont'd)	EH32678 T140V	rocker shaft 'O' ring leaking	1100
	AH24362 TR7RV	rocker/r primary gasket	1650
	JH15793 T100R	top end leaking	961
	DH30693 TR7RV	high gear seal leak	1925
	EH32394 T140V	tappet guide block 'O' ring leaking	1291
	BH26427 T140V	r/r base gasket	1866
	CH28675 TR7RV	oil leak from contact breaker seal	1238
	CH27351 T140V	oil sending unit leaking	1266
	EH33096 T140V	c/c joint l. h. oil leak	300
	XH02604 TRX75	contact breaker oil leak	912
	KH16760 TR5T	many top end oil leaks	1430
	NH17980 TR7RV	contact breaker seal leaking	1507
	GH34891 TR7RV	high gear oil seal leak	8
	GH34891 TR7RV	oil leak contact breakers seal	8
	DH30665 TR7RV	leak at oil pressure switch	50
	NH00205 TRX75	contact breaker seal leak	332
	CH03157 T150V	oil leak between head and cylinder	2480
	XH21450 TR7RV	oil leak from both rocker boxes	761
	XH21450 TR7RV	oil leak from tach drive unit	761
	CH13332 T150V	valve cover gasket leaking	2004
	AH23555 T140V	r/r base gasket	1581
	PH01207 TRX75	r/r inner and outer prim. gaskets	109
	CH29399 TR7RV	replace mainshaft seal	2800
	BH26718 T140V	top end oil leak	560
	BH25575 T140V	oil pressure switch leaking	618
	EH33360 T140V	rocker box leaking	1538
	EH33462 T140V	timing cover leak	101
	DH04097 T150V	oil pressure sending unit leaking	1225
	DH32257 T140V	petcock cut top oil leak	150
	DH32141 T140V	oil leak at cylinder base gasket	835
	DH31569 T140V	top end oil leak	791
	CH03563 T150V	oil leak rocker box to head joint	520
	EH33549 T140V	leak at timing cover	538
	EH04836 T150V	oil leak in rocker boxes	284
	BH25424 T140V	oil pressure switch leak	1348
	CH27695 TR7RV	r/r base gasket leak	1146
	NH18527 T100R	oil leak from rocker box to head	920
	CH26944 T140V	pressure switch leaks	500
	BH25673 T140V	numerous top end oil leaks	799
	CH22111 T140V	oil pressure switch leak	635
	EH32781 T140V	oil leak ex tappet guide block	1468
	DH29922 TR7RV	rocker box oil leak	894
	NH18016 TR7RV	oil leak at point seal	3800
	JH15668 T100R	oil pressure switch leak	536
	CH28597 TR7RV	high gear oil seal leak	550
	CH28597 TR7RV	contact breaker oil leak	550
	CH28597 TR7RV	oil leak at transmission inner/outer	550
	NH17940 TR7RV	oil pressure switch leak	484

Category	Engine No.	Problem	Mileage	
Oil Leaks (cont'd)	NG04104 T150V	oil leak at cylinder base	592	
	GH35255 TR7RV	r/r primary gasket	7	
	DH03743 T150V	both r/box to head joints leaking	515	
	BH26248 T140V	high gear oil seal leak	1800	
	DH32126 T140V	oil leak at r/box to head joint	1705	
	DH32126 T140V	high gear oil seal leak	1705	
	DH31942 T140V	oil leak at point seal	848	
	PH01452 TRX75	oil leak at prim. chain case inner case	1305	
	CH03152 T150V	oil leak valve covers	1310	
	DH30546 TR7RV	pressure switch leaks	930	
	AH25208 T140V	oil leak at cylinder base	979	
	AH25208 T140V	oil leak at rocker boxes	979	
	DH31588 T140V	leaky rocker boxes	746	
	EH32618 T140V	point oil seal leaking	728	
	EH32618 T140V	r/r primary gasket	728	
	CH29629 TR7RV	r/r primary gasket	0	
	CH27365 T140V	base gasket leak	720	
	DH32026 T140V	oil leak from timing cover	351	
	DH32026 T140V	r/r primary gasket	351	
	DH31981 T140V	oil leak at tappet guide block	504	
	EH32507 T140V	oil leak at tappet guide block	615	
	XH01637 T150V	many top end oil leaks	5944	
	EH32558 T140V	pressure switch leaks	10	
	EH32558 T140V	contact breaker seal leaking	10	
	BH25557 T140V	contact breaker seal leakage	2711	
	NH17842 T140V	r/r primary gasket	2600	
	JH16277 T100R	rocker box oil leak	3780	
	PETROL TANKS/	CH28931 TR7RV	carburetor leaking	774
	PETCOCKS/FUEL LINES	DH03560 T150V	fuel taps leaking	559
		EH32618 T140V	gas lines leaking	1072
		NH17842 T140V	gas tap leaking	2600
		DH32026 T140V	nut for fuel line broken	351
		EH32427 T140V	fuel lines leak	659
	PH19794 TR5T	fuel tank leak, R/R tank	2499	
	DH31524 T140RV	two leaking petcocks	401	
	EH32419 T140V	fuel pipes leaking	667	
	CH03491 T150V	gas tank leaking at petcock openings	508	
	PH00978 TRX75	gas tank leaking at petcock	1272	
	AH23945 TR7RV	fuel lines leaking	1830	
	AH24775 TR7RV	petcocks seeping	857	
	XH22264 T140V	petcock leaking	527	
	DH29886 TR7RV	back of fuel tank leaks	2680	
	CH27408 T140V	petrol pipe leaks	2100	

Category	Engine No.	Problem	Mileage
PETROL TANKS/	DH31870 T140V	leak in fuel line	518
PETCOCKS/FUEL LINES	BH26308 T140V	leaking fuel lines	521
	EH32883 T140V	gas leaks at petcock mounting	778
	BH25746 T140V	fuel line too short	1900
	BH25428 T140V	gas tap leaking	1101
	XH21524 TR7RV	fuel tank tap defective	517
	AH24507 T140V	petcocks leak	1693
	DH32092 T140V	fuel lines leaking	1498
	AH24958 T140V	fuel tank leak	2319
	EH32737 T140V	fuel line leakage	1451
	DH31977 T140V	fuel tank from fuel pipe	6
	CH03353 T150V	gas tank leaking at petcock opening	2285
	AH25143 T140V	gas leaks	150
	XH02712 TRX75	gas tank leak, reglass	402
	CH26952 T140V	petcock leaking	2150
	AH25040 T140RV	gas leak on both carbs	1827
	EH32741 T140V	gas leaking from carb	527
	CH03372 T150V	gas tank leaking at petcocks	1232
	KH22672 T140V	gas line leaking at clamp	3471
	PH01443 TRX75	gas tank leaking badly at gas filler	1749
	CH27928 TR7RV	both petcocks leaking	842
	EH32601 T140V	fuel tap leaking	858
	CH03507 T150V	both petcocks leaking	1686
	JH15960 T100R	petcocks leaking gas	663
	JH15879 T100R	gas cap leaking	605
	AH01720 T150V	both petcocks leaking	1300
	DH31752 T140V	petcocks leaking	1218
	DH32167 T140V	petcocks leak	1288
	AH23999 TR7RV	fuel line leaking	682
	AH18901 T100R	fuel tank leaking	202
	CH29036 TR7RV	gas tank leaking at petcock	1045
	EH05041 T150V	fuel tank leaking at gas taps	2
	EH33558 T140V	gas line leaking at clamps	7
	PH20619 TR5T	fuel tank leak	0
	EH32467 T140V	gas lines leaked	4
	AH24191 TR7RV	small imperfection in side of tank	632
	AH23582 T140V	fuel line nut cracked	2718
	AH23245 T140V	reecrimp fuel lines	1633
	PH20489 TR5T	connection on gas line was cracked	874
	JH15885 T100R	rear mount broke off	3310
	EH32520 T140V	gas leaks at gasline clamps	4
	NH18568 T100R	tab broken on fuel tank	1423
	KH17092 TR5T	petcock leaks	750
	EH32768 T140V	gas line was leaking	491
	DH31826 T140V	leaky petcocks	1200
SPEEDOMETER/	EH32678 T140V	tach drive plug came out	1100
TACHOMETERS	DH29939 TR7RV	plug came out of tach drive	1954
	DH31725 T140V	R/R E5157 tach drive gear	1935
	JH15193 T100R	speedo. trip meter not working	961
	CH28675 TR7RV	plug came out of tach drive	1238
	EH32394 T140V	tach. drive is broken	1291
	DH31660 T140V	plug came out of tach drive	2600
	BH26238 T140V	plug in tach. drive fell out	5300

Page 31

Category	Engine No.	Problem	Mileage
Speedometer/	BH00790 T150V	erratic speedo	554
Tachometers	EH32746 T140V	tach. cable broken	598
(con't)	XH21705 TR7RV	plug came out of tach drive	1623
	AH24504 T140V	plug and spacer came out of t/drive	361
	DH29961 TR7RV	tach drive frozen	562
	BH25557 T140V	bad speedo	2711
	CH30634 TR7RV	plug came out of t/drive	605
	EH32563 T140V	plug came out of t/drive	643
	DH31906 T140V	tach drive fell apart	1407
	CH26851 T140V	Welch plug came out of t/drive	1525
	CH26832 T140V	tach drive broken	316
	EH32746 T140V	plug came out of t/drive	1245
	DH32178 T140V	plug came out of tach drive	n/a
	BH25506 T140V	frozen tach drive	101
	DH30555 TR7RV	plug came out of t/gearbox	3589
	AH23926 TR7RV	plug came out of t/drive	1720
	CH27284 T140V	plug came out of t/gearbox	680
	NH00294 TRX75	speedo erratic	1888
	CH03768 T150V	trip indicator will not work	1088
	CH27930 TR7RV	broken tach drive	991
	BH25878 T140V	Welch washer fell off	926
	DH31752 T140V	tach drive fell apart	1218
	KH16987 TR5T	tach cable broken	1015
	EH33002 T140V	tach drive came apart	1320
	CH28618 TR7RV	Welch washer & spacer fell out	464
	CH27054 T140V	tach gearbox failure	2397
	CH28690 TR7RV	plug on bottom t/drive missing	4206
	CH26951 T140V	E12481 plug fell out	1731
	AH23980 TR7RV	E12481 plug fell out of t/drive	652
	CH28581 TR7RV	Welch plug came out	1743
	CH29813 TR7RV	trip mileage would not work	1277
	BH25730 T140V	tach gearbox came apart	1161
	AH25188 T140V	tach drive plug fell out	2020
	AH25053 T140V	plug out of t/drive	602
	NH00266 TRX75	tach & speedo reading incoorectly	2022
	BH25591 T140V	plug came out	1506
	DH29951 TR7RV	plug came out of t/gearbox	720
	AH24651 TR7RV	plug came out	637
	CH27549 T140V	Welch plug came out	998
	AH24323 T140V	Welch plug came out	1035
	AH23910 TR7RV	tach cable was broken	490
	XH21580 TR7RV	Welch plug came out	1821
	EH33480 T140V	Welch washer replaced on t/drive	940
	DH31544 T140V	Welch washer replaced on t/drive	1057
	CH27110 T140V	t/gearbox broken	947
	EH33213 T140V	tach drive broken	762
	EH32562 T140V	tach drive broken	1448
	DH30445 TR7RV	washer, spacer came out of t/drive	1250
	AH23994 TR7RV	speedo seized	3390
	XH01033 T150V	speedo does not work	3954
	DH30312 TR7RV	tach drive broken	3106
	XH02600 TRX75	defective speedo	732

Page 32

Category	Engine No.	Problem	Mileage
Speedometer/	CH03507 T150V	speedo gearbox drive broken	1686
Tachometer	NH00193 TRX75	odometer broken	871
(cont'd)	DH31966 T140V	trip meter sticks	1504
	JH15672 T100R	tach seized	1200
	CH28975 TR7RV	erratic speedo	220
	DH29979 TR7RV	replaced plug, spacer in t/drive	2996
	AH25093 T140V	plug fell out of t/drive	1580
	PH01463 TRX75	speedo would not register	2300
	CH03624 T150V	cracked l/s panel F14856	625
	EH32313 T140V	tach drive plug fell out	913
	CH29485 TR7RV	tach drive fell apart	1162
	BH25506 T140V	plug dropped out of t/drive	75
	AH24273 TR7RV	t/gearbox fell out	5601
	CH29379 TR7RV	tach drive plug fell out	664
	CH27706 TR7RV	speedo trip mileage not working	2783
	PH18886 T100R	tach does not read correctly	785
	AH25143 T140V	speedo not operative	4208
	NH18503 T100R	speedo broken	730
	DH32134 T140V	gears fell out of tach drive	559
	XH02587 TRX75	erratic speedo	908
	BH26591 T140V	speedo erratic	1282
	DH31893 T140V	Welch plug fell out	885
	CH26883 T140V	trip odometer not working	1700
	CH26883 T140V	Welch plug fell out	1700
	EH33270 T140V	tach g/box washer fell out	1161
	CH29630 TR7RV	plug in tach drive fell out	1820
	DH31657 T140V	tach g/box fell apart	575
	XH21095 TR7RV	erratic speedo	5697
	PH18908 T100R	speedo erratic	5215
	PH19169 TR5T	tach erratic	518
	DH29829 TR7RV	odometer does not work	85
	NH01222 TRX75	speedo erratic	2836
	BH25566 T140V	tach g/b Welch plug fell out	1356
	DH20615 TR5T	broken tach cable	1401
	PH19238 TR5T	speedo cable broken	524
	DH30062 TR7RV	odometer malfunctioning	472
	DH31705 T140V	t/drive fell apart	527
	XH00428 T150V	speedo drive no good	3320
	BH25457 T140V	tach drive broken	3400
	AH23943 TR7RV	bottom came out of t/drive box	1354
	JH15656 T100R	tach erratic	1262
	PH19794 TR5T	screw fell out of tach	1250
	CH27033 T140V	E5757 tach gear broken	823
	NH00476 TRX75	erratic speedo	2420
	NH00476 TRX75	odometer on repl. unit not working	2420
	CH29699 TR7RV	t/drive fell apart	1026
	BH26023 T140V	speedo erratic	2419
	PH18822 T100R	speedo erratic	1215
	XH21522 TR7RV	trip milage does not record	1721
	AH25117 T140V	erratic speedo	1562

Category	Engine No.	Problem	Mileage
SPEEDOMETER/	BH25853 T140V	tach. drive gear broke	1117
TACHOMETER (con't)	PH31663 T140V	alternator grommet leaks	0
	EH32681 T140V	plug came out of tach drive	315
	KH16539 T100R	trip meter inoperative	1491
	AH01001 TR7RV	speedo not registering	98
	DH31569 T140V	tach. drive fell apart	791
	EH33290 T140V	tach. drive broke	1321
	DH31889 T140V	tach. plug fell out	2100
	AH24330 TR7RV	tach. drive unit fell apart	187
	CH27409 T140V	welch washer in tach. drive failed	1140
	BH26200 T140RV	tach. gearbox fell apart	950
	CH27298 T140V	plug came out of tach. drive	2149
	DH25855 T140V	tach. drive gearbox fell apart	2864
	CH28654 TR7RV	freeze plug came out of tach drive	641
	JH15992 T100R	speedo erratic	10
	JH15740 T100R	erratic speedo	3329
	EH32853 T140V	plug came out of tach. drive	1378
	CH27829 TR7RV	plug came out of tach drive	1142
	BH26221 T140V	plug came out of tach. drive	1547
	DH30254 TR7RV	plug came out of tach. drive	522
	CH28909 TR7RV	the welch plug came out of bottom of tach.	1020
	CH27182 T140V	E12475 tach. gear broke	1028
	AH25044 T140V	bottom plug fell out of tach. body	3000
	PH18709 T100R	bad speedo	638
	BH26647 T140V	tach drive fell apart	710
	EH32655 T140V	tach. drive plug and spacer falls out	796
	EH33072 T140V	tach. drive gear came out	848
	PH18934 T100R	speedo. will not go above 60 M.P.H.	2125
	CH27773 TR7RV	welch plug missing on tach drive	518
	CH29469 TR7RV	defective speedo. cable	500
	CH29348 TR7RV	faulty speedo drive	1500
	DH31677 T140V	plug out of tack drive	1100
	EH33194 T140RV	battery falling out of tack drive	2167
	PH00957 TRX75	speedo wouldn't work	3683
	DH30519 TR7RV	welch plug missing from tach gearbox	232
	AH24782 TR7RV	welch plug missing from tach gearbox	2103
	EH32419 T140V	tachometer gear box fell apart	667
	DH31663 T140V	plug came out of T/D	1112
	BH25447 T140V	tach drive broken	1489
	AH25207 T140V	bottom plug fell out	2460
	BH26606 T140V	tach drive came apart	2263
	CH27089 T140RV	tach. gear box came apart	3365
	EH32803 T140V	welch plug fell out of bottom of gearbox	589
	CH28364 TR7RV	plug on end of tach. came off	1025
	CH28894 TR7RV	broken tachometer drive	1755
	AH23945 TR7RV	tach. gearbox fell apart	1830
	CH29782 TR7RV	tach. gearbox welch plug fell out	4145
	DH31692 T140RV	tach drive broken	1604
	CH27408 T140V	tach drive welch plug fell out	2100
	DH31870 T140V	tach inoperative	518
	XH22366 T140V	speedometer cable broken	1803
	BH26308 T140V	plug came out of tach drive	521
	EH32544 T140V	tach drive came apart	876

Category	Engine No.	Problem	Mileage
SPEEDOMETER/	AH23499 T140V	speedo cable broke	1240
TACHOMETER (con't)	EH32331 T140RV	plug came out of tach drive	1409
	BH25746 T140V	plug came out of tach drive	1900
	CH29219 TR7RV	tach. drive box plug missing	1455
	CH26991 T140RV	E5157 Tach gear broke	1657
TIRES	EH32552 T140V	wobbler, R/R front tire	531
	CH27870 TR7RV	tire was out of round.	640
	CH27736 TR7RV	defective rear inner tube	266
	DH30512 TR7RV	tube caught in rim lock	87
	JH15617 T100R	hole in inner tube	637
	AH24177 T140RV	rear tire not round	508
	BH05143 T150V	leak in rear inner tube	19
	AH24977 T140V	flaw in front tire	2599
	AH24135 TR7RV	rear tire was cracked	2120
	DH31795 T140V	bad thread on front tire	520
	BH26027 T140V	rear tube leaks	580
	DH30123 TR7RV	rear tire defective	2283
	PH20497 TR5T	front tire split	1060
	KH16661 TR5T	small holes in rear tube	53
	NH00267 TRX75	rear tire defect	1737
	EH32756 T140V	tube in rear tire pinched	0
	EH33334 T140V	slow leak in rear tire	0
	XH20836 TR5T	slow leak in front tire	0
	PH00887 TRX75	defective tire - front	1200
	CH29722 TR7RV	slow leak in rear tube	8
	JH15644 T100R	air leaking out of front tire	883
	EH32864 T140V	front tire out of round	497