

# The TRIUMPH Corporation

## SERVICE BULLETIN

BULLETIN NO. 21

January 5, 1967

SUBJECT: Replacement Parts Catalog No. 8 for 1967 "C" Range Twins

We list below important corrections and additions that should be made in your book immediately.

IMPORTANT NOTE: Always check the remarks column at the far right of each odd-numbered page in the parts catalog for additional information when ordering. This column identifies the particular model the part fits if it is not universal through-  
out the range. ONLY the T100R and T100C models are supplied in the U.S.

<u>Page No.</u>	<u>Ref. No.</u>	<u>Corrections and additions</u>
12		DELETE: E6908 Piston Complete. Not fitted to U.S. Models. DELETE: E6899 Piston Complete. Not fitted to U.S. Models. DELETE: E6906 Piston Complete. Not fitted to U.S. Models. DELETE: SPL76 Carton Pack (order individual items) DELETE: SPL77 " " " " " ADD: GST100/65-66 Overhaul Gasket Set.
13		NOTE: Triumph Paint stocked <u>ONLY</u> in aerosol containers.
15	13-15	DELETE: Individual Rings not available. Use CDL65 Ring Set for T100's.
	21	DELETE: 5h21582h Rotor. Order 5h213901 Rotor which is interchangeable.
23		DELETE: Entire Page. Not supplied in U.S.
25		DELETE: Entire Page. Not supplied in U.S.
31		ADD: E4819 Dowel Pin, exhaust cam to auto-advance unit. ADD: h25370 Base Plate, for contact breaker assembly. ADD: 5h933228 Lead, contact set to coil.
33		ADD: T37320 Heavy Duty Index Plunger Spring.
31	3	NOTE: DELETE fitted to T100C, D4819E fitted to T100R.

<u>Page No.</u>	<u>Ref. No.</u>	<u>Corrections and Additions</u>	
49	9	ADD:	6105L165 Damper Unit, for 6105L164 Suspension Unit.
		DELETE:	61053946. Not fitted to U.S. models.
51	8	NOTE:	F6738 Lock c/w Key not supplied with top lug.
53	3 20-29	NOTE:	F6738 Lock c/w Key not supplied with top lug.
		DELETE:	Entire section. Not fitted to U.S. Models.
55	1 2 3 4 24+25	DELETE:	W1664. Not fitted to U.S. Models.
		DELETE:	W1870. Not fitted to U.S. Models.
		DELETE:	W1873. Not fitted to U.S. Models.
		DELETE:	W1897. Not fitted to U.S. Models.
		DELETE:	W1213 Linings and W129 Rivets. Not stocked. Use CP38/AM2 Carton Packs.
56	1 2 3 27-28	DELETE:	W1741. Not fitted to U.S. Models.
		DELETE:	W1479. Not fitted to U.S. Models.
		DELETE:	W1471. Not fitted to U.S. Models.
		DELETE:	W1213 Linings and W129 Rivets. Not stocked. Use CP38/AM2 Carton Pack.
		ADD:	21-832-5300-1 Pinion Gear for D373 Gearbox.
		ADD:	3L-333-530-1 End Plug for D373 Gearbox.
59		DELETE:	Entire Page. Not fitted to U.S. Models.
61	5 17 20 38-41 1-20	DELETE:	H1482. Not fitted to U.S. Models.
		DELETE:	F5921 Number Plate. Not fitted to U.S. Models.
		DELETE:	F5981 Rear Mudguard. Not fitted to U.S. Models.
		DELETE:	Front Number Plate. Not fitted to U.S. Models.
		NOTE:	Specify year, model, and color scheme when ordering PAINTED Parts.
63	16 17	DELETE:	F7776. Not fitted to U.S. Models.
		DELETE:	F7777. Not fitted to U.S. Models.
		ADD:	Eyelets for T100C LEFT and PANEL
			F7036 8575 H961 Eyelet Part 985MME 3
65	1 10 15 16 21 27	DELETE:	F7393. Not fitted to U.S. Models.
		DELETE:	F1717. Not fitted to U.S. Models.
		DELETE:	F3917. Not fitted to U.S. Models.
		DELETE:	F2936. Not fitted to U.S. Models.
		DELETE:	F3220. Not fitted to U.S. Models.
		NOTE:+	Specify model when ordering gas tanks, i.e., T100C i.e., T100B or T100C.

January 5, 1957

<u>Page No.</u>	<u>Ref. No.</u>	<u>Corrections and Additions</u>	
67	10	DELETE:	7449L. Not stocked. Use CD31 Tubing.
-----			
69	18 31-36 40 41	CHANGE: DELETE: DELETE: DELETE:	D311 to DA311. Tire Inflator. Not fitted to U.S. Models. W330. Not fitted to U.S. Models. 74811. Not fitted to U.S. Models.
-----			
71	1 13 22	DELETE: DELETE: DELETE: ADD:	W1871. Not fitted to U.S. Models. 18/999. Not fitted to U.S. Models. 18/1000. Not fitted to U.S. Models. 51981009 Lead, for horn push and dip switch.
-----			
73	7 13 13 19-26	CHANGE: CHANGE: DELETE: DELETE:	D560 to D330T. D565 to D466T. D566. Not fitted to U.S. Models. D499 and components. Not fitted to U.S. Models.
-----			
79	13	CHANGE: ADD: ADD: ADD:	31071 to 31107. 51111104 Clip, at ends of L5119 coil. 511119L6 Lamination, for L5119 coil. 51523480 Shell, for 59699 Headlamp.
-----			
81	18 35 28-29	DELETE: CHANGE: DELETE: ADD:	D262. Use D105T. 70197 to 70183. High Tension Leads not stocked. Use standard 7mm cable. L239L7 Bracket, for L5110 coil.
-----			
83	8 54 32-42 50	ADD: ADD: DELETE: DELETE: ADD: ADD: ADD: add;	51520540 Adaptor Unit, complete with leads. Part Number D622 (Specify Key number). 5345L Lamp and Components. Not fitted to U.S. Models. 12768L. Use 11071L. 51523508 Headlight Shell, for 5973L Headlamp. 511300L1 Nut, for 31899 Ignition Switch. 51938986 Fuse Assembly. CD392, 30 amp fuse (box of five) CD417, 20 amp fuse (box of five)

(OVER)

<u>Page No.</u>	<u>Ref. No.</u>	<u>Correction and Additions</u>
25	1	DELETE: 334500/00. Not fitted to U.S. Models.
	18	DELETE: 35156. Not available.
	19	DELETE: E5155. Not available.
	26	DELETE: E6124. Not available.
		ADD: 31-325-135 Brass Fitting for instruments at cable connection.
		<u>NOTE:</u> SMITH'S SPEEDOMETERS are standard equipment on all 1967 "C" Range models. VDC ENDURO SPEEDOMETERS are available if desired, but at dealer's or customer's expense. See TRI-COR accessory catalog for ordering information.